Sample no.	Analysis	Compound	Conc	Rad uncrt	Units	Q flags	Matrix	Type location	Depth (ft)	Sample date
HG521501F7	RAD	Ra-226	1.2	0.17	pCi/g	J	SOIL	SA 33	0-1	10/9/97
HG522601F7	RAD	Ra-226	1.19	0.11	pCi/g	J	SOIL	SA 44	0-1	10/9/97
HG522101F7	RAD	Ra-226	1.18	0.11	pCi/g	J	SOIL	SA 39	0-1	10/9/97
HG522801F7	RAD	Ra-226	1.14	0.11	pCi/g	J	SOIL	SA 46	0-1	10/9/97
HG520101F7	RAD	Ra-226	1.13	0.08	pCi/g	J	SOIL	SA 19	0-1	10/8/97
HG521201F7	RAD	Ra-226	1.12	0.10	pCi/g	J	SOIL	SA 30	0-1	10/9/97
HG521001F7	RAD	Ra-226	1.09	0.09	pCi/g	J	SOIL	SA 28	0-1	10/8/97
HG521701F7	RAD	Ra-226	1.09	0.08	pCi/g	J	SOIL	SA 36	0-1	10/9/97
HG521101F7	RAD	Ra-226	1.08	0.10	pCi/g	J	SOIL	SA 29	0-1	10/8/97
HG521801F7	RAD	Ra-226	1.08	0.10	pCi/g	J	SOIL	SA 36	0-1	10/9/97
HG522001F7	RAD	Ra-226	1.08	0.10	pCi/g	J	SOIL	SA 38	0-1	10/9/97
HG522501F7	RAD	Ra-226	1.07	0.11	pCi/g	J	SOIL	SA 43	0-1	10/9/97
HG521901F7	RAD	Ra-226	1.06	0.08	pCi/g	J	SOIL	SA 37	0-1	10/9/97
HG522401F7	RAD	Ra-226	1.06	0.11	pCi/g	J	SOIL	SA 42	0-1	10/9/97
HG520102F7	RAD	Ra-226	1.06	0.09	pCi/g	J	SOIL	SA 19	0-1	10/8/97
HG520801F7	RAD	Ra-226	1.06	0.10	pCi/g	J	SOIL	SA 26	0-1	10/8/97
HG520701F7	RAD	Ra-226	1.05	0.09	pCi/g	J	SOIL	SA 25	0-1	10/8/97
HG522301F7	RAD	Ra-226	1.05	0.08	pCi/g	J	SOIL	SA 41	0-1	10/9/97
HG522201F7	RAD	Ra-226	1.04	0.09	pCi/g	J	SOIL	SA 40	0-1	10/9/97
HG520601F7	RAD	Ra-226	1.04	0.09	pCi/g	J	SOIL	SA 24	0-1	10/8/97
HG521301F7	RAD	Ra-226	1.03	0.10	pCi/g	J	SOIL	SA 31	0-1	10/9/97
HG521601F7	RAD	Ra-226	1.02	0.10	pCi/g	J	SOIL	SA 34	0-1	10/9/97
HG521401F7	RAD	Ra-226	1.01	0.11	pCi/g	J	SOIL	SA 32	0-1	10/9/97
HG520001F7	RAD	Ra-226	1.00	0.07	pCi/g	J	SOIL	SA 18	0-1	10/8/97
HG520901F7	RAD	Ra-226	0.973	0.10	pCi/g	J	SOIL	SA 27	0-1	10/8/97
HG520401F7	RAD	Ra-226	0.96	0.10	pCi/g	J	SOIL	SA 22	0-1	10/8/97
HG520201F7	RAD	Ra-226	0.93	0.08	pCi/g	J	SOIL	SA 20	0-1	10/8/97
HG520301F7	RAD	Ra-226	0.926	0.08	pCi/g	J	SOIL	SA 21	0-1	10/8/97
HG520501F7	RAD	Ra-226	0.912	0.08	pCi/g	J	SOIL	SA 23	0-1	10/8/97
4CC01801R4	RAD	Ra-226	1.7	0.57	pCi/g	J	SOIL	POND 15	2-4	5/15/97
4CP06101R4	RAD	Ra-226	2.31	0.35	pCi/g	J	SOIL	PIPE 2	2-4	5/15/97
4CC01101R4	RAD	Ra-226	3.39	0.47	pCi/g	J	SOIL	POND 9	3-5	5/15/97
4CN03801R4	RAD	Ra-226	1.8	0.47	pCi/g	J	SOIL	TRENCH 1 #4	3.5	6/2/97
4CN04301R4	RAD	Ra-226	1.29	0.50	pCi/g	J	SOIL	TRENCH 2 #1	3.5	6/2/97
4CC00301R4	RAD	Ra-226	3.38	0.45	pCi/g	J	SOIL	POND 2	3.5-5.5	5/15/97
4CN03501R4	RAD	Ra-226	1.58	0.78	pCi/g	J	SOIL	TRENCH 1 #1	4	6/2/97
4CN03701R4	RAD	Ra-226	2.05	0.73	pCi/g	J	SOIL	TRENCH 1 #3	4	6/2/97
4CN03601R4	RAD	Ra-226	1.65	0.84	pCi/g	J	SOIL	TRENCH 1 #2	4.5	6/2/97
4CN03602R4	RAD	Ra-226	1.54	0.83	pCi/g	J	SOIL	TRENCH 1 #2	4.5	6/2/97
4CN05101R4	RAD	Ra-226	1.65	0.55	pCi/g	J	SOIL	TRENCH 3 #1	5.6	6/2/97
4CN05201R4	RAD	Ra-226	1.48	0.63	pCi/g	J	SOIL	TRENCH 3 #2	6	6/2/97
4CN05401R4	RAD	Ra-226	4.15	0.86	pCi/g	J	SOIL	TRENCH 3 #4	6.5	6/2/97
4CN05301R4	RAD	Ra-226	2.01	0.86	pCi/g	J	SOIL	TRENCH 3 #3	6.8	6/2/97
4CN04601R4	RAD	Ra-226	2.19	0.66	pCi/g	J	SOIL	TRENCH 2 #4	7	6/2/97
4CN04501R4	RAD	Ra-226	2.64	0.74	pCi/g	J	SOIL	TRENCH 2 #3	7.5	6/2/97
4CN04401R4	RAD	Ra-226	1.9	0.74	pCi/g	J	SOIL	TRENCH 2 #2	8	6/2/97
HG522102F7	RAD	Ru-103	0.0712	0.04	pCi/g	U	SOIL	SA 39	0-1	10/9/97
HG521601F7	RAD	Ru-103	0.043	0.02	pCi/g	UJ	SOIL	SA 34	0-1	10/9/97
HG521401F7	RAD	Ru-103	0.0403	0.02	pCi/g	U	SOIL	SA 32	0-1	10/9/97
HG520301F7	RAD	Ru-103	0.0277	0.01	pCi/g	UJ	SOIL	SA 21	0-1	10/8/97
HG520601F7	RAD	Ru-103	0.0277	0.02	pCi/g	U	SOIL	SA 24	0-1	10/8/97
HG521301F7	RAD	Ru-103	0.0242	0.02	pCi/g	U	SOIL	SA 31	0-1	10/9/97
HG522401F7	RAD	Ru-103	0.0231	0.02	pCi/g	U	SOIL	SA 42	0-1	10/9/97
HG521101F7	RAD	Ru-103	0.017	0.02	pCi/g	U	SOIL	SA 29	0-1	10/8/97
HG522301F7	RAD	Ru-103	0.0167	0.01	pCi/g	U	SOIL	SA 41	0-1	10/9/97
HG521901F7	RAD	Ru-103	0.0124	0.01	pCi/g	U	SOIL	SA 37	0-1	10/9/97
HG520401F7	RAD	Ru-103	0.0123	0.02	pCi/g	U	SOIL	SA 22	0-1	10/8/97
HG522801F7	RAD	Ru-103	0.012	0.02	pCi/g	U	SOIL	SA 46	0-1	10/9/97
HG520001F7	RAD	Ru-103	0.00608	0.01	pCi/g	U	SOIL	SA 18	0-1	10/8/97
HG520501F7	RAD	Ru-103	0.00582	0.01	pCi/g	U	SOIL	SA 23	0-1	10/8/97
HG520701F7	RAD	Ru-103	0.00271	0.02	pCi/g	U	SOIL	SA 25	0-1	10/8/97

Sample no.	Analysis	Compound	Conc	Rad uncrt	Units	Q flags	Matrix	Type location	Depth (ft)	Sample date
HG520201F7	RAD	Ru-103	0.00267	0.01	pCi/g	U	SOIL	SA 20	0-1	10/8/97
HG522201F7	RAD	Ru-103	0.00213	0.02	pCi/g	U	SOIL	SA 40	0-1	10/9/97
HG522901F7	RAD	Ru-103	-0.00237	0.02	pCi/g	U	SOIL	SA 47	0-1	10/9/97
HG522701F7	RAD	Ru-103	-0.00365	0.02	pCi/g	U	SOIL	SA 45	0-1	10/9/97
HG521001F7	RAD	Ru-103	-0.0049	0.02	pCi/g	U	SOIL	SA 28	0-1	10/8/97
HG520101F7	RAD	Ru-103	-0.00518	0.01	pCi/g	U	SOIL	SA 19	0-1	10/8/97
HG520102F7	RAD	Ru-103	-0.00781	0.01	pCi/g	U	SOIL	SA 19	0-1	10/8/97
HG521701F7	RAD	Ru-103	-0.00786	0.01	pCi/g	U	SOIL	SA 36	0-1	10/9/97
HG520901F7	RAD	Ru-103	-0.00899	0.02	pCi/g	U	SOIL	SA 27	0-1	10/8/97
HG520801F7	RAD	Ru-103	-0.0114	0.02	pCi/g	U	SOIL	SA 26	0-1	10/8/97
HG521201F7	RAD	Ru-103	-0.0118	0.02	pCi/g	U	SOIL	SA 30	0-1	10/9/97
HG522501F7	RAD	Ru-103	-0.0138	0.02	pCi/g	U	SOIL	SA 43	0-1	10/9/97
HG522101F7	RAD	Ru-103	-0.0141	0.02	pCi/g	U	SOIL	SA 39	0-1	10/9/97
HG522001F7	RAD	Ru-103	-0.0156	0.02	pCi/g	U	SOIL	SA 38	0-1	10/9/97
HG522601F7	RAD	Ru-103	-0.0178	0.02	pCi/g	U	SOIL	SA 44	0-1	10/9/97
HG521501F7	RAD	Ru-103	-0.018	0.04	pCi/g	U	SOIL	SA 33	0-1	10/9/97
HG521801F7	RAD	Ru-103	-0.0218	0.02	pCi/g	U	SOIL	SA 36	0-1	10/9/97
4CC01801R4	RAD	Ru-103	0.0164	0.02	pCi/g	U	SOIL	POND 15	2-4	5/15/97
4CP06101R4	RAD	Ru-103	-0.0107	0.01	pCi/g	U	SOIL	PIPE 2	2-4	5/15/97
4CC01101R4	RAD	Ru-103	0.0087	0.02	pCi/g	U	SOIL	POND 9	3-5	5/15/97
4CN03801R4	RAD	Ru-103	0.0483	0.03	pCi/g	U	SOIL	TRENCH 1 #4	3.5	6/2/97
4CN04301R4	RAD	Ru-103	-0.0337	0.03	pCi/g	U	SOIL	TRENCH 2 #1	3.5	6/2/97
4CC00301R4	RAD	Ru-103	0.0015	0.01	pCi/g	U	SOIL	POND 2	3.5-5.5	5/15/97
4CN03501R4	RAD	Ru-103	-0.0333	0.04	pCi/g	U	SOIL	TRENCH 1 #1	4	6/2/97
4CN03701R4	RAD	Ru-103	-0.0092	0.04	pCi/g	U	SOIL	TRENCH 1 #3	4	6/2/97
4CN03601R4	RAD	Ru-103	0.0011	0.03	pCi/g	U	SOIL	TRENCH 1 #2	4.5	6/2/97
4CN03602R4	RAD	Ru-103	0.0548	0.04	pCi/g	U	SOIL	TRENCH 1 #2	4.5	6/2/97
4CN05101R4	RAD	Ru-103	0.0042	0.03	pCi/g	U	SOIL	TRENCH 3 #1	5.6	6/2/97
4CN05201R4	RAD	Ru-103	0.0462	0.03	pCi/g	U	SOIL	TRENCH 3 #2	6	6/2/97
4CN05401R4	RAD	Ru-103	0.0189	0.04	pCi/g	U	SOIL	TRENCH 3 #4	6.5	6/2/97
4CN05301R4	RAD	Ru-103	0.0475	0.03	pCi/g	U	SOIL	TRENCH 3 #3	6.8	6/2/97
4CN04601R4	RAD	Ru-103	-0.044	0.03	pCi/g	U	SOIL	TRENCH 2 #4	7	6/2/97
4CN04501R4	RAD	Ru-103	0.0075	0.03	pCi/g	U	SOIL	TRENCH 2 #3	7.5	6/2/97
4CN04401R4	RAD	Ru-103	0.0062	0.03	pCi/g	U	SOIL	TRENCH 2 #2	8	6/2/97
HG521301F7	RAD	Ru-106	0.206	0.16	pCi/g	U	SOIL	SA 31	0-1	10/9/97
HG520201F7	RAD	Ru-106	0.196	0.11	pCi/g	U	SOIL	SA 20	0-1	10/8/97
HG522101F7	RAD	Ru-106	0.18	0.14	pCi/g	U	SOIL	SA 39	0-1	10/9/97
HG522901F7	RAD	Ru-106	0.17	0.17	pCi/g	U	SOIL	SA 47	0-1	10/9/97
HG520401F7	RAD	Ru-106	0.146	0.13	pCi/g	U	SOIL	SA 22	0-1	10/8/97
HG520901F7	RAD	Ru-106	0.139	0.17	pCi/g	U	SOIL	SA 27	0-1	10/8/97
HG520102F7	RAD	Ru-106	0.134	0.11	pCi/g	U	SOIL	SA 19	0-1	10/8/97
HG520101F7	RAD	Ru-106	0.113	0.10	pCi/g	U	SOIL	SA 19	0-1	10/8/97
HG520301F7	RAD	Ru-106	0.112	0.11	pCi/g	U	SOIL	SA 21	0-1	10/8/97
HG521401F7	RAD	Ru-106	0.104	0.17	pCi/g	U	SOIL	SA 32	0-1	10/9/97
HG521801F7	RAD	Ru-106	0.0735	0.15	pCi/g	U	SOIL	SA 36	0-1	10/9/97
HG522201F7	RAD	Ru-106	0.0707	0.14	pCi/g	U	SOIL	SA 40	0-1	10/9/97
HG522501F7	RAD	Ru-106	0.0673	0.14	pCi/g	U	SOIL	SA 43	0-1	10/9/97
HG520501F7	RAD	Ru-106	0.0409	0.18	pCi/g	U	SOIL	SA 23	0-1	10/8/97
HG520801F7	RAD	Ru-106	0	0.31	pCi/g	U	SOIL	SA 26	0-1	10/8/97
HG520001F7	RAD	Ru-106	-0.00386	0.07	pCi/g	U	SOIL	SA 18	0-1	10/8/97
HG520601F7	RAD	Ru-106	-0.0157	0.15	pCi/g	U	SOIL	SA 24	0-1	10/8/97
HG521601F7	RAD	Ru-106	-0.0167	0.17	pCi/g	U	SOIL	SA 34	0-1	10/9/97
HG522301F7	RAD	Ru-106	-0.0601	0.11	pCi/g	U	SOIL	SA 41	0-1	10/9/97
HG522401F7	RAD	Ru-106	-0.0634	0.15	pCi/g	U	SOIL	SA 42	0-1	10/9/97
HG522801F7	RAD	Ru-106	-0.0634	0.16	pCi/g	U	SOIL	SA 46	0-1	10/9/97
HG522001F7	RAD	Ru-106	-0.0647	0.13	pCi/g	U	SOIL	SA 38	0-1	10/9/97
HG521501F7	RAD	Ru-106	-0.0738	0.25	pCi/g	U	SOIL	SA 33	0-1	10/9/97
HG521001F7	RAD	Ru-106	-0.0837	0.14	pCi/g	U	SOIL	SA 28	0-1	10/8/97
HG522701F7	RAD	Ru-106	-0.106	0.14	pCi/g	U	SOIL	SA 45	0-1	10/9/97
HG521701F7	RAD	Ru-106	-0.113	0.08	pCi/g	U	SOIL	SA 36	0-1	10/9/97
HG521101F7	RAD	Ru-106	-0.121	0.15	pCi/g	U	SOIL	SA 29	0-1	10/8/97

Sample no.	Analysis	Compound	Conc	Rad uncrt	Units	Q flags	Matrix	Type location	Depth (ft)	Sample date
HG521901F7	RAD	Ru-106	-0.131	0.10	pCi/g	U	SOIL	SA 37	0-1	10/9/97
HG521201F7	RAD	Ru-106	-0.139	0.16	pCi/g	U	SOIL	SA 30	0-1	10/9/97
HG520701F7	RAD	Ru-106	-0.312	0.13	pCi/g	U	SOIL	SA 25	0-1	10/8/97
HG522601F7	RAD	Ru-106	-0.355	0.15	pCi/g	U	SOIL	SA 44	0-1	10/9/97
HG522102F7	RAD	Ru-106	-0.385	0.29	pCi/g	U	SOIL	SA 39	0-1	10/9/97
4CC01801R4	RAD	Ru-106	0.0393	0.15	pCi/g	U	SOIL	POND 15	2-4	5/15/97
4CP06101R4	RAD	Ru-106	-0.102	0.09	pCi/g	U	SOIL	PIPE 2	2-4	5/15/97
4CC01101R4	RAD	Ru-106	-0.113	0.14	pCi/g	U	SOIL	POND 9	3-5	5/15/97
4CN03801R4	RAD	Ru-106	0.07	0.15	pCi/g	U	SOIL	TRENCH 1 #4	3.5	6/2/97
4CN04301R4	RAD	Ru-106	-0.17	0.19	pCi/g	U	SOIL	TRENCH 2 #1	3.5	6/2/97
4CC00301R4	RAD	Ru-106	0.125	0.12	pCi/g	U	SOIL	POND 2	3.5-5.5	5/15/97
4CN03501R4	RAD	Ru-106	0.224	0.26	pCi/g	U	SOIL	TRENCH 1 #1	4	6/2/97
4CN03701R4	RAD	Ru-106	0.144	0.21	pCi/g	U	SOIL	TRENCH 1 #3	4	6/2/97
4CN03601R4	RAD	Ru-106	0.407	0.23	pCi/g	U	SOIL	TRENCH 1 #2	4.5	6/2/97
4CN03602R4	RAD	Ru-106	-0.124	0.28	pCi/g	U	SOIL	TRENCH 1 #2	4.5	6/2/97
4CN05101R4	RAD	Ru-106	0	0.24	pCi/g	U	SOIL	TRENCH 3 #1	5.6	6/2/97
4CN05201R4	RAD	Ru-106	0.0875	0.21	pCi/g	U	SOIL	TRENCH 3 #2	6	6/2/97
4CN05401R4	RAD	Ru-106	-0.488	0.24	pCi/g	U	SOIL	TRENCH 3 #4	6.5	6/2/97
4CN05301R4	RAD	Ru-106	-0.0641	0.24	pCi/g	U	SOIL	TRENCH 3 #3	6.8	6/2/97
4CN04601R4	RAD	Ru-106	-0.0753	0.18	pCi/g	U	SOIL	TRENCH 2 #4	7	6/2/97
4CN04501R4	RAD	Ru-106	-0.182	0.19	pCi/g	U	SOIL	TRENCH 2 #3	7.5	6/2/97
4CN04401R4	RAD	Ru-106	-0.0316	0.22	pCi/g	U	SOIL	TRENCH 2 #2	8	6/2/97
HG521501F7	RAD	Sb-125	0.138	0.08	pCi/g	U	SOIL	SA 33	0-1	10/9/97
HG521801F7	RAD	Sb-125	0.107	0.08	pCi/g	U	SOIL	SA 36	0-1	10/9/97
HG520801F7	RAD	Sb-125	0.101	0.04	pCi/g	UJ	SOIL	SA 26	0-1	10/8/97
HG520901F7	RAD	Sb-125	0.0655	0.05	pCi/g	U	SOIL	SA 27	0-1	10/8/97
HG520701F7	RAD	Sb-125	0.052	0.05	pCi/g	U	SOIL	SA 25	0-1	10/8/97
HG521001F7	RAD	Sb-125	0.0507	0.05	pCi/g	U	SOIL	SA 28	0-1	10/8/97
HG522401F7	RAD	Sb-125	0.0443	0.04	pCi/g	U	SOIL	SA 42	0-1	10/9/97
HG520301F7	RAD	Sb-125	0.0426	0.03	pCi/g	U	SOIL	SA 21	0-1	10/8/97
HG520201F7	RAD	Sb-125	0.0425	0.03	pCi/g	U	SOIL	SA 20	0-1	10/8/97
HG520601F7	RAD	Sb-125	0.0415	0.05	pCi/g	U	SOIL	SA 24	0-1	10/8/97
HG520401F7	RAD	Sb-125	0.0371	0.04	pCi/g	U	SOIL	SA 22	0-1	10/8/97
HG520001F7	RAD	Sb-125	0.0313	0.02	pCi/g	U	SOIL	SA 18	0-1	10/8/97
HG520501F7	RAD	Sb-125	0.0231	0.03	pCi/g	U	SOIL	SA 23	0-1	10/8/97
HG520102F7	RAD	Sb-125	0.023	0.04	pCi/g	U	SOIL	SA 19	0-1	10/8/97
HG521301F7	RAD	Sb-125	0.0226	0.04	pCi/g	U	SOIL	SA 31	0-1	10/9/97
HG521701F7	RAD	Sb-125	0.0213	0.02	pCi/g	U	SOIL	SA 36	0-1	10/9/97
HG522101F7	RAD	Sb-125	0.0206	0.05	pCi/g	U	SOIL	SA 39	0-1	10/9/97
HG522601F7	RAD	Sb-125	0.018	0.04	pCi/g	U	SOIL	SA 44	0-1	10/9/97
HG521201F7	RAD	Sb-125	0.0109	0.04	pCi/g	U	SOIL	SA 30	0-1	10/9/97
HG521901F7	RAD	Sb-125	0	0.04	pCi/g	U	SOIL	SA 37	0-1	10/9/97
HG522301F7	RAD	Sb-125	-0.00508	0.03	pCi/g	U	SOIL	SA 41	0-1	10/9/97
HG522501F7	RAD	Sb-125	-0.00563	0.04	pCi/g	U	SOIL	SA 43	0-1	10/9/97
HG521101F7	RAD	Sb-125	-0.00664	0.05	pCi/g	U	SOIL	SA 29	0-1	10/8/97
HG521401F7	RAD	Sb-125	-0.007	0.04	pCi/g	U	SOIL	SA 32	0-1	10/9/97
HG522701F7	RAD	Sb-125	-0.00866	0.04	pCi/g	U	SOIL	SA 45	0-1	10/9/97
HG522201F7	RAD	Sb-125	-0.0103	0.04	pCi/g	U	SOIL	SA 40	0-1	10/9/97
HG520101F7	RAD	Sb-125	-0.0231	0.03	pCi/g	U	SOIL	SA 19	0-1	10/8/97
HG522901F7	RAD	Sb-125	-0.0515	0.06	pCi/g	U	SOIL	SA 47	0-1	10/9/97
HG522801F7	RAD	Sb-125	-0.0796	0.05	pCi/g	U	SOIL	SA 46	0-1	10/9/97
HG522001F7	RAD	Sb-125	-0.103	0.04	pCi/g	U	SOIL	SA 38	0-1	10/9/97
HG521601F7	RAD	Sb-125	-0.107	0.05	pCi/g	U	SOIL	SA 34	0-1	10/9/97
HG522102F7	RAD	Sb-125	-0.149	0.08	pCi/g	U	SOIL	SA 39	0-1	10/9/97
4CC01801R4	RAD	Sb-125	0.0388	0.04	pCi/g	U	SOIL	POND 15	2-4	5/15/97
4CP06101R4	RAD	Sb-125	-0.0164	0.02	pCi/g	U	SOIL	PIPE 2	2-4	5/15/97
4CC01101R4	RAD	Sb-125	-0.0074	0.04	pCi/g	U	SOIL	POND 9	3-5	5/15/97
4CN03801R4	RAD	Sb-125	0.0047	0.04	pCi/g	U	SOIL	TRENCH 1 #4	3.5	6/2/97
4CN04301R4	RAD	Sb-125	0.0531	0.05	pCi/g	U	SOIL	TRENCH 2 #1	3.5	6/2/97
4CC00301R4	RAD	Sb-125	-0.0154	0.03	pCi/g	U	SOIL	POND 2	3.5-5.5	5/15/97
4CN03501R4	RAD	Sb-125	-0.0825	0.06	pCi/g	U	SOIL	TRENCH 1 #1	4	6/2/97

Sample no.	Analysis	Compound	Conc	Rad uncrt	Units	Q flags	Matrix	Type location	Depth (ft)	Sample date
4CN03701R4	RAD	Sb-125	-0.0815	0.05	pCi/g	U	SOIL	TRENCH 1 #3	4	6/2/97
4CN03601R4	RAD	Sb-125	-0.0862	0.07	pCi/g	U	SOIL	TRENCH 1 #2	4.5	6/2/97
4CN03602R4	RAD	Sb-125	-0.0096	0.06	pCi/g	U	SOIL	TRENCH 1 #2	4.5	6/2/97
4CN05101R4	RAD	Sb-125	-0.0056	0.06	pCi/g	U	SOIL	TRENCH 3 #1	5.6	6/2/97
4CN05201R4	RAD	Sb-125	-0.02	0.06	pCi/g	U	SOIL	TRENCH 3 #2	6	6/2/97
4CN05401R4	RAD	Sb-125	-0.064	0.06	pCi/g	U	SOIL	TRENCH 3 #4	6.5	6/2/97
4CN05301R4	RAD	Sb-125	0.0084	0.05	pCi/g	U	SOIL	TRENCH 3 #3	6.8	6/2/97
4CN04601R4	RAD	Sb-125	0.14	0.05	pCi/g	UJ	SOIL	TRENCH 2 #4	7	6/2/97
4CN04501R4	RAD	Sb-125	0.0597	0.06	pCi/g	U	SOIL	TRENCH 2 #3	7.5	6/2/97
4CN04401R4	RAD	Sb-125	-0.107	0.05	pCi/g	U	SOIL	TRENCH 2 #2	8	6/2/97
40400101C1	INORG	Selenium	0.93		mg/kg	U	SOIL	INLET 1	0-0.5	7/18/95
40400301C1	INORG	Selenium	0.82		mg/kg	U	SOIL	INLET 2	0-0.5	7/18/95
40400501C1	INORG	Selenium	0.84		mg/kg	U	SOIL	INLET 3	0-0.5	7/18/95
40400701C1	INORG	Selenium	0.82		mg/kg	U	SOIL	INLET 4	0-0.5	7/18/95
4CC03501LM	INORG	Selenium	0.3		mg/kg	UWN	SOIL	POND 32	0-0.5	7/16/97
4CC03601LM	INORG	Selenium	0.44		mg/kg	BN	SOIL	POND 33	0-0.5	7/16/97
4CC03701LM	INORG	Selenium	1.1		mg/kg	BSN	SOIL	POND 34	0-0.5	7/16/97
4CC03801LM	INORG	Selenium	0.31		mg/kg	UWN	SOIL	POND 35	0-0.5	7/16/97
4CC03901LM	INORG	Selenium	0.31		mg/kg	UWN	SOIL	POND 36	0-0.5	7/16/97
4CC04001LM	INORG	Selenium	0.31		mg/kg	UWN	SOIL	POND 37	0-0.5	7/16/97
4CC04002LM	INORG	Selenium	3.1		mg/kg	UWN	SOIL	POND 37	0-0.5	7/16/97
40400201C1	INORG	Selenium	0.84		mg/kg	U	SOIL	INLET 2	0.17-0.67	7/18/95
40400202C1	INORG	Selenium	0.93		mg/kg	U	SOIL	INLET 2	0.17-0.67	7/18/95
40400401C1	INORG	Selenium	0.85		mg/kg	U	SOIL	INLET 2	0.17-0.67	7/18/95
HG522601C1	INORG	Selenium	1.2		mg/kg	P	SOIL	SA 44	0-1	10/9/97
HG524101C1	INORG	Selenium	1		mg/kg	NJ P	SOIL	SA 59	0-1	10/13/97
HG523001C1	INORG	Selenium	0.96		mg/kg	B P	SOIL	SA 48	0-1	10/9/97
HG524102C1	INORG	Selenium	0.9		mg/kg	NJ P	SOIL	SA 59	0-1	10/13/97
HG521101C1	INORG	Selenium	0.9		mg/kg	BNJ P	SOIL	SA 29	0-1	10/8/97
HG520201C1	INORG	Selenium	0.83		mg/kg	BNJ P	SOIL	SA 20	0-1	10/8/97
HG523801C1	INORG	Selenium	0.81		mg/kg	NJ P	SOIL	SA 56	0-1	10/13/97
HG522901C1	INORG	Selenium	0.79		mg/kg	B P	SOIL	SA 47	0-1	10/9/97
HG523101C1	INORG	Selenium	0.79		mg/kg	B P	SOIL	SA 49	0-1	10/9/97
HG521601C1	INORG	Selenium	0.79		mg/kg	B P	SOIL	SA 34	0-1	10/9/97
HG521901C1	INORG	Selenium	0.79		mg/kg	B P	SOIL	SA 37	0-1	10/9/97
HG520102C1	INORG	Selenium	0.78		mg/kg	BNJ P	SOIL	SA 19	0-1	10/8/97
HG521001C1	INORG	Selenium	0.78		mg/kg	BNJ P	SOIL	SA 28	0-1	10/8/97
HG522801C1	INORG	Selenium	0.78		mg/kg	B P	SOIL	SA 46	0-1	10/9/97
HG524001C1	INORG	Selenium	0.76		mg/kg	BNJ P	SOIL	SA 57	0-1	10/13/97
HG521301C1	INORG	Selenium	0.76		mg/kg	B P	SOIL	SA 31	0-1	10/9/97
HG521801C1	INORG	Selenium	0.76		mg/kg	B P	SOIL	SA 36	0-1	10/9/97
HG523401C1	INORG	Selenium	0.75		mg/kg	B P	SOIL	SA 52	0-1	10/13/97
HG522102C1	INORG	Selenium	0.75		mg/kg	B P	SOIL	SA 39	0-1	10/9/97
HG522501C1	INORG	Selenium	0.74		mg/kg	B P	SOIL	SA 43	0-1	10/9/97
HG520301C1	INORG	Selenium	0.74		mg/kg	BNJ P	SOIL	SA 21	0-1	10/8/97
HG521501C1	INORG	Selenium	0.73		mg/kg	B P	SOIL	SA 33	0-1	10/9/97
HG522701C1	INORG	Selenium	0.71		mg/kg	B P	SOIL	SA 45	0-1	10/9/97
HG523201C1	INORG	Selenium	0.7		mg/kg	B P	SOIL	SA 50	0-1	10/13/97
HG523701C1	INORG	Selenium	0.68		mg/kg	B P	SOIL	SA 55	0-1	10/13/97
HG522301C1	INORG	Selenium	0.68		mg/kg	B P	SOIL	SA 41	0-1	10/9/97
HG522401C1	INORG	Selenium	0.67		mg/kg	B P	SOIL	SA 42	0-1	10/9/97
HG520101C1	INORG	Selenium	0.67		mg/kg	BNJ P	SOIL	SA 19	0-1	10/8/97
HG520701C1	INORG	Selenium	0.67		mg/kg	BNJ P	SOIL	SA 25	0-1	10/8/97
HG523301C1	INORG	Selenium	0.67		mg/kg	B P	SOIL	SA 51	0-1	10/13/97
HG520001C1	INORG	Selenium	0.65		mg/kg	BNJ P	SOIL	SA 18	0-1	10/8/97
HG520501C1	INORG	Selenium	0.65		mg/kg	BNJ P	SOIL	SA 23	0-1	10/8/97
HG522001C1	INORG	Selenium	0.64		mg/kg	B P	SOIL	SA 38	0-1	10/9/97
HG524401C1	INORG	Selenium	0.63		mg/kg	B P	SOIL	SA 62	0-1	10/13/97
HG521701C1	INORG	Selenium	0.63		mg/kg	B P	SOIL	SA 36	0-1	10/9/97
HG523801C1	INORG	Selenium	0.62		mg/kg	BNJ P	SOIL	SA 56	0-1	10/13/97
HG523901C1	INORG	Selenium	0.61		mg/kg	BNJ P	SOIL	SA 57	0-1	10/13/97

Sample no.	Analysis	Compound	Conc	Rad uncrt	Units	Q flags	Matrix	Type location	Depth (ft)	Sample date
HG520401C1	INORG	Selenium	0.61		mg/kg	BNJ P	SOIL	SA 22	0-1	10/8/97
HG524201C1	INORG	Selenium	0.6		mg/kg	BNJ P	SOIL	SA 60	0-1	10/13/97
HG522101C1	INORG	Selenium	0.58		mg/kg	B P	SOIL	SA 39	0-1	10/9/97
HG520601C1	INORG	Selenium	0.57		mg/kg	BNJ P	SOIL	SA 24	0-1	10/8/97
HG523601C1	INORG	Selenium	0.57		mg/kg	B P	SOIL	SA 54	0-1	10/13/97
HG521401C1	INORG	Selenium	0.56		mg/kg	B P	SOIL	SA 32	0-1	10/9/97
HG524301C1	INORG	Selenium	0.52		mg/kg	B P	SOIL	SA 61	0-1	10/13/97
HG520901C1	INORG	Selenium	0.51		mg/kg	BNJ P	SOIL	SA 27	0-1	10/8/97
HG523501C1	INORG	Selenium	0.5		mg/kg	B P	SOIL	SA 53	0-1	10/13/97
HG520801C1	INORG	Selenium	0.5		mg/kg	BNJ P	SOIL	SA 26	0-1	10/8/97
HG522201C1	INORG	Selenium	0.45		mg/kg	B P	SOIL	SA 40	0-1	10/9/97
HG521201C1	INORG	Selenium	0.39		mg/kg	B P	SOIL	SA 30	0-1	10/9/97
40400601C1	INORG	Selenium	0.96		mg/kg	U	SOIL	INLET 3	1.5	7/18/95
40400801C1	INORG	Selenium	0.99		mg/kg	U	SOIL	INLET 4	1.5	7/18/95
4CN03801C1	INORG	Selenium	0.28		mg/kg	NUJ	SOIL	TRENCH 1 #4	3.5	6/2/97
4CN04301C1	INORG	Selenium	0.47		mg/kg	BWNJ	SOIL	TRENCH 2 #1	3.5	6/2/97
4CN03501C1	INORG	Selenium	0.42		mg/kg	BWNJ	SOIL	TRENCH 1 #1	4	6/2/97
4CN03701C1	INORG	Selenium	0.3		mg/kg	NUJ	SOIL	TRENCH 1 #3	4	6/2/97
4CN03601C1	INORG	Selenium	0.31		mg/kg	NUJ	SOIL	TRENCH 1 #2	4.5	6/2/97
4CN03602C1	INORG	Selenium	0.45		mg/kg	BNJ	SOIL	TRENCH 1 #2	4.5	6/2/97
4CN05101C1	INORG	Selenium	0.29		mg/kg	WNUJ	SOIL	TRENCH 3 #1	5.6	6/2/97
4CN05201C1	INORG	Selenium	0.36		mg/kg	WNUJ	SOIL	TRENCH 3 #2	6	6/2/97
4CN05401C1	INORG	Selenium	0.32		mg/kg	WNUJ	SOIL	TRENCH 3 #4	6.5	6/2/97
4CN05301C1	INORG	Selenium	3.9		mg/kg	BNJ	SOIL	TRENCH 3 #3	6.8	6/2/97
4CN04601C1	INORG	Selenium	0.27		mg/kg	NUJ	SOIL	TRENCH 2 #4	7	6/2/97
4CN04501C1	INORG	Selenium	0.32		mg/kg	BNJ	SOIL	TRENCH 2 #3	7.5	6/2/97
4CN04401C1	INORG	Selenium	1.2		mg/kg	SNUJ	SOIL	TRENCH 2 #2	8	6/2/97
40400101C1	INORG	Silver	1.7		mg/kg	BN*UJ	SOIL	INLET 1	0-0.5	7/18/95
40400301C1	INORG	Silver	0.96		mg/kg	BN*UJ	SOIL	INLET 2	0-0.5	7/18/95
40400501C1	INORG	Silver	1.6		mg/kg	BN*UJ	SOIL	INLET 3	0-0.5	7/18/95
40400701C1	INORG	Silver	4.8		mg/kg	N*UJ	SOIL	INLET 4	0-0.5	7/18/95
4CC03501LM	INORG	Silver	9.9		mg/kg		SOIL	POND 32	0-0.5	7/16/97
4CC03601LM	INORG	Silver	6.5		mg/kg		SOIL	POND 33	0-0.5	7/16/97
4CC03701LM	INORG	Silver	121		mg/kg		SOIL	POND 34	0-0.5	7/16/97
4CC03801LM	INORG	Silver	2.3		mg/kg		SOIL	POND 35	0-0.5	7/16/97
4CC03901LM	INORG	Silver	3.6		mg/kg		SOIL	POND 36	0-0.5	7/16/97
4CC04001LM	INORG	Silver	10.2		mg/kg		SOIL	POND 37	0-0.5	7/16/97
4CC04002LM	INORG	Silver	12.9		mg/kg		SOIL	POND 37	0-0.5	7/16/97
40400201C1	INORG	Silver	9.1		mg/kg	N*UJ	SOIL	INLET 2	0.17-0.67	7/18/95
40400202C1	INORG	Silver	3.1		mg/kg	N*UJ	SOIL	INLET 2	0.17-0.67	7/18/95
40400401C1	INORG	Silver	2.5		mg/kg	N*UJ	SOIL	INLET 2	0.17-0.67	7/18/95
40400601C1	INORG	Silver	0.87		mg/kg	BN*UJ	SOIL	INLET 3	1.5	7/18/95
40400801C1	INORG	Silver	0.51		mg/kg	BN*UJ	SOIL	INLET 4	1.5	7/18/95
HG523001C1	INORG	Silver	0.41		mg/kg	B P	SOIL	SA 48	0-1	10/9/97
HG524102C1	INORG	Silver	0.4		mg/kg	B P	SOIL	SA 59	0-1	10/13/97
HG522601C1	INORG	Silver	0.36		mg/kg	B P	SOIL	SA 44	0-1	10/9/97
HG520101C1	INORG	Silver	0.34		mg/kg	B P	SOIL	SA 19	0-1	10/8/97
HG522901C1	INORG	Silver	0.34		mg/kg	B P	SOIL	SA 47	0-1	10/9/97
HG523601C1	INORG	Silver	0.34		mg/kg	B P	SOIL	SA 54	0-1	10/13/97
HG520301C1	INORG	Silver	0.33		mg/kg	B P	SOIL	SA 21	0-1	10/8/97
HG524101C1	INORG	Silver	0.32		mg/kg	B P	SOIL	SA 59	0-1	10/13/97
HG523701C1	INORG	Silver	0.31		mg/kg	B P	SOIL	SA 55	0-1	10/13/97
HG524201C1	INORG	Silver	0.31		mg/kg	B P	SOIL	SA 60	0-1	10/13/97
HG523301C1	INORG	Silver	0.3		mg/kg	B P	SOIL	SA 51	0-1	10/13/97
HG521701C1	INORG	Silver	0.3		mg/kg	B P	SOIL	SA 36	0-1	10/9/97
HG521801C1	INORG	Silver	0.3		mg/kg	B P	SOIL	SA 36	0-1	10/9/97
HG522401C1	INORG	Silver	0.3		mg/kg	B P	SOIL	SA 42	0-1	10/9/97
HG522102C1	INORG	Silver	0.29		mg/kg	B P	SOIL	SA 39	0-1	10/9/97
HG522201C1	INORG	Silver	0.29		mg/kg	B P	SOIL	SA 40	0-1	10/9/97
HG522301C1	INORG	Silver	0.29		mg/kg	B P	SOIL	SA 41	0-1	10/9/97
HG520401C1	INORG	Silver	0.29		mg/kg	B P	SOIL	SA 22	0-1	10/8/97

Sample no.	Analysis	Compound	Conc	Rad uncrt	Units	Q flags	Matrix	Type location	Depth (ft)	Sample date
HG523501C1	INORG	Silver	0.29		mg/kg	B P	SOIL	SA 53	0-1	10/13/97
HG522801C1	INORG	Silver	0.28		mg/kg	B P	SOIL	SA 46	0-1	10/9/97
HG521601C1	INORG	Silver	0.28		mg/kg	B P	SOIL	SA 34	0-1	10/9/97
HG520102C1	INORG	Silver	0.28		mg/kg	B P	SOIL	SA 19	0-1	10/8/97
HG520201C1	INORG	Silver	0.27		mg/kg	B P	SOIL	SA 20	0-1	10/8/97
HG520801C1	INORG	Silver	0.27		mg/kg	B P	SOIL	SA 26	0-1	10/8/97
HG522701C1	INORG	Silver	0.27		mg/kg	B P	SOIL	SA 45	0-1	10/9/97
HG521001C1	INORG	Silver	0.27		mg/kg	B P	SOIL	SA 28	0-1	10/8/97
HG521101C1	INORG	Silver	0.26		mg/kg	B P	SOIL	SA 29	0-1	10/8/97
HG521901C1	INORG	Silver	0.26		mg/kg	B P	SOIL	SA 37	0-1	10/9/97
HG522101C1	INORG	Silver	0.26		mg/kg	B P	SOIL	SA 39	0-1	10/9/97
HG523101C1	INORG	Silver	0.25		mg/kg	B P	SOIL	SA 49	0-1	10/9/97
HG524401C1	INORG	Silver	0.24		mg/kg	B P	SOIL	SA 62	0-1	10/13/97
HG523201C1	INORG	Silver	0.23		mg/kg	B P	SOIL	SA 50	0-1	10/13/97
HG521201C1	INORG	Silver	0.23		mg/kg	B P	SOIL	SA 30	0-1	10/9/97
HG521401C1	INORG	Silver	0.23		mg/kg	B P	SOIL	SA 32	0-1	10/9/97
HG521301C1	INORG	Silver	0.22		mg/kg	B P	SOIL	SA 31	0-1	10/9/97
HG522501C1	INORG	Silver	0.2		mg/kg	B P	SOIL	SA 43	0-1	10/9/97
HG520601C1	INORG	Silver	0.2		mg/kg	B P	SOIL	SA 24	0-1	10/8/97
HG521501C1	INORG	Silver	0.19		mg/kg	B P	SOIL	SA 33	0-1	10/9/97
HG523401C1	INORG	Silver	0.19		mg/kg	B P	SOIL	SA 52	0-1	10/13/97
HG523801N2	INORG	Silver	0.18		mg/kg	B P	SOIL	SA 56	0-1	10/13/97
HG523901C1	INORG	Silver	0.18		mg/kg	B P	SOIL	SA 57	0-1	10/13/97
HG524301C1	INORG	Silver	0.18		mg/kg	B P	SOIL	SA 61	0-1	10/13/97
HG522001C1	INORG	Silver	0.18		mg/kg	B P	SOIL	SA 38	0-1	10/9/97
HG520001C1	INORG	Silver	0.17		mg/kg	B P	SOIL	SA 18	0-1	10/8/97
HG520501C1	INORG	Silver	0.17		mg/kg	B P	SOIL	SA 23	0-1	10/8/97
HG523801C1	INORG	Silver	0.16		mg/kg	B P	SOIL	SA 56	0-1	10/13/97
HG520901C1	INORG	Silver	0.16		mg/kg	B P	SOIL	SA 27	0-1	10/8/97
HG520701C1	INORG	Silver	0.15		mg/kg	B P	SOIL	SA 25	0-1	10/8/97
HG524001C1	INORG	Silver	0.14		mg/kg	B P	SOIL	SA 57	0-1	10/13/97
4CN03801C1	INORG	Silver	1.5		mg/kg	U	SOIL	TRENCH 1 #4	3.5	6/2/97
4CN04301C1	INORG	Silver	1.6		mg/kg	U	SOIL	TRENCH 2 #1	3.5	6/2/97
4CN03501C1	INORG	Silver	1.6		mg/kg	U	SOIL	TRENCH 1 #1	4	6/2/97
4CN03701C1	INORG	Silver	1.5		mg/kg	U	SOIL	TRENCH 1 #3	4	6/2/97
4CN03601C1	INORG	Silver	1.4		mg/kg	U	SOIL	TRENCH 1 #2	4.5	6/2/97
4CN03602C1	INORG	Silver	1.5		mg/kg	U	SOIL	TRENCH 1 #2	4.5	6/2/97
4CN05101C1	INORG	Silver	1.5		mg/kg	UJ	SOIL	TRENCH 3 #1	5.6	6/2/97
4CN05201C1	INORG	Silver	1.4		mg/kg	UJ	SOIL	TRENCH 3 #2	6	6/2/97
4CN05401C1	INORG	Silver	1.5		mg/kg	UJ	SOIL	TRENCH 3 #4	6.5	6/2/97
4CN05301C1	INORG	Silver	1.6		mg/kg	UJ	SOIL	TRENCH 3 #3	6.8	6/2/97
4CN04601C1	INORG	Silver	1.5		mg/kg	UJ	SOIL	TRENCH 2 #4	7	6/2/97
4CN04501C1	INORG	Silver	1.4		mg/kg	U	SOIL	TRENCH 2 #3	7.5	6/2/97
4CN04401C1	INORG	Silver	1.5		mg/kg	U	SOIL	TRENCH 2 #2	8	6/2/97
40400101C1	INORG	Sodium	308		mg/kg	R	SOIL	INLET 1	0-0.5	7/18/95
40400301C1	INORG	Sodium	137		mg/kg	R	SOIL	INLET 2	0-0.5	7/18/95
40400501C1	INORG	Sodium	275		mg/kg	R	SOIL	INLET 3	0-0.5	7/18/95
40400701C1	INORG	Sodium	267		mg/kg	R	SOIL	INLET 4	0-0.5	7/18/95
4CC03501LM	INORG	Sodium	151		mg/kg	B	SOIL	POND 32	0-0.5	7/16/97
4CC03601LM	INORG	Sodium	184		mg/kg	B	SOIL	POND 33	0-0.5	7/16/97
4CC03701LM	INORG	Sodium	153		mg/kg	B	SOIL	POND 34	0-0.5	7/16/97
4CC03801LM	INORG	Sodium	145		mg/kg	B	SOIL	POND 35	0-0.5	7/16/97
4CC03901LM	INORG	Sodium	167		mg/kg	B	SOIL	POND 36	0-0.5	7/16/97
4CC04001LM	INORG	Sodium	138		mg/kg	B	SOIL	POND 37	0-0.5	7/16/97
4CC04002LM	INORG	Sodium	151		mg/kg	B	SOIL	POND 37	0-0.5	7/16/97
40400201C1	INORG	Sodium	235		mg/kg	R	SOIL	INLET 2	0.17-0.67	7/18/95
40400202C1	INORG	Sodium	356		mg/kg	R	SOIL	INLET 2	0.17-0.67	7/18/95
40400401C1	INORG	Sodium	181		mg/kg	R	SOIL	INLET 2	0.17-0.67	7/18/95
HG524102C1	INORG	Sodium	1360		mg/kg	P	SOIL	SA 59	0-1	10/13/97
HG523601C1	INORG	Sodium	1270		mg/kg	P	SOIL	SA 54	0-1	10/13/97
HG524101C1	INORG	Sodium	1220		mg/kg	P	SOIL	SA 59	0-1	10/13/97

Sample no.	Analysis	Compound	Conc	Rad uncrt	Units	Q flags		Matrix	Type location	Depth (ft)	Sample date
HG523401C1	INORG	Sodium	1020		mg/kg		P	SOIL	SA 52	0-1	10/13/97
HG523101C1	INORG	Sodium	867		mg/kg	B	P	SOIL	SA 49	0-1	10/9/97
HG524201C1	INORG	Sodium	803		mg/kg	B	P	SOIL	SA 60	0-1	10/13/97
HG521901C1	INORG	Sodium	769		mg/kg	B	P	SOIL	SA 37	0-1	10/9/97
HG521801C1	INORG	Sodium	697		mg/kg	B	P	SOIL	SA 36	0-1	10/9/97
HG520801C1	INORG	Sodium	673		mg/kg	B	P	SOIL	SA 26	0-1	10/8/97
HG520301C1	INORG	Sodium	667		mg/kg	B	P	SOIL	SA 21	0-1	10/8/97
HG522601C1	INORG	Sodium	661		mg/kg	B	P	SOIL	SA 44	0-1	10/9/97
HG520601C1	INORG	Sodium	605		mg/kg	B	P	SOIL	SA 24	0-1	10/8/97
HG523001C1	INORG	Sodium	543		mg/kg	B	P	SOIL	SA 48	0-1	10/9/97
HG521401C1	INORG	Sodium	538		mg/kg	B	P	SOIL	SA 32	0-1	10/9/97
HG520101C1	INORG	Sodium	538		mg/kg	B	P	SOIL	SA 19	0-1	10/8/97
HG520201C1	INORG	Sodium	522		mg/kg	B	P	SOIL	SA 20	0-1	10/8/97
HG520701C1	INORG	Sodium	516		mg/kg	B	P	SOIL	SA 25	0-1	10/8/97
HG520102C1	INORG	Sodium	510		mg/kg	B	P	SOIL	SA 19	0-1	10/8/97
HG523301C1	INORG	Sodium	507		mg/kg	B	P	SOIL	SA 51	0-1	10/13/97
HG520901C1	INORG	Sodium	505		mg/kg	B	P	SOIL	SA 27	0-1	10/8/97
HG524401C1	INORG	Sodium	502		mg/kg	B	P	SOIL	SA 62	0-1	10/13/97
HG521501C1	INORG	Sodium	485		mg/kg	B	P	SOIL	SA 33	0-1	10/9/97
HG522901C1	INORG	Sodium	484		mg/kg	B	P	SOIL	SA 47	0-1	10/9/97
HG521201C1	INORG	Sodium	478		mg/kg	B	P	SOIL	SA 30	0-1	10/9/97
HG523501C1	INORG	Sodium	474		mg/kg	B	P	SOIL	SA 53	0-1	10/13/97
HG522701C1	INORG	Sodium	474		mg/kg	B	P	SOIL	SA 45	0-1	10/9/97
HG521101C1	INORG	Sodium	470		mg/kg	B	P	SOIL	SA 29	0-1	10/8/97
HG520401C1	INORG	Sodium	464		mg/kg	B	P	SOIL	SA 22	0-1	10/8/97
HG521601C1	INORG	Sodium	456		mg/kg	B	P	SOIL	SA 34	0-1	10/9/97
HG521001C1	INORG	Sodium	450		mg/kg	B	P	SOIL	SA 28	0-1	10/8/97
HG522801C1	INORG	Sodium	450		mg/kg	B	P	SOIL	SA 46	0-1	10/9/97
HG521701C1	INORG	Sodium	447		mg/kg	B	P	SOIL	SA 36	0-1	10/9/97
HG521301C1	INORG	Sodium	446		mg/kg	B	P	SOIL	SA 31	0-1	10/9/97
HG522201C1	INORG	Sodium	442		mg/kg	B	P	SOIL	SA 40	0-1	10/9/97
HG523701C1	INORG	Sodium	429		mg/kg	B	P	SOIL	SA 55	0-1	10/13/97
HG523201C1	INORG	Sodium	426		mg/kg	B	P	SOIL	SA 50	0-1	10/13/97
HG522501C1	INORG	Sodium	426		mg/kg	B	P	SOIL	SA 43	0-1	10/9/97
HG520501C1	INORG	Sodium	421		mg/kg	B	P	SOIL	SA 23	0-1	10/8/97
HG522102C1	INORG	Sodium	419		mg/kg	B	P	SOIL	SA 39	0-1	10/9/97
HG522301C1	INORG	Sodium	415		mg/kg	B	P	SOIL	SA 41	0-1	10/9/97
HG522101C1	INORG	Sodium	409		mg/kg	B	P	SOIL	SA 39	0-1	10/9/97
HG523801C1	INORG	Sodium	408		mg/kg	B	P	SOIL	SA 56	0-1	10/13/97
HG520001C1	INORG	Sodium	405		mg/kg	B	P	SOIL	SA 18	0-1	10/8/97
HG522401C1	INORG	Sodium	391		mg/kg	B	P	SOIL	SA 42	0-1	10/9/97
HG523901C1	INORG	Sodium	374		mg/kg	B	P	SOIL	SA 57	0-1	10/13/97
HG522001C1	INORG	Sodium	372		mg/kg	B	P	SOIL	SA 38	0-1	10/9/97
HG524301C1	INORG	Sodium	346		mg/kg	B	P	SOIL	SA 61	0-1	10/13/97
HG524001C1	INORG	Sodium	345		mg/kg	B	P	SOIL	SA 57	0-1	10/13/97
HG523801N2	INORG	Sodium	343		mg/kg	B	P	SOIL	SA 56	0-1	10/13/97
40400601C1	INORG	Sodium	323		mg/kg		R	SOIL	INLET 3	1.5	7/18/95
40400801C1	INORG	Sodium	382		mg/kg		R	SOIL	INLET 4	1.5	7/18/95
4CN03801C1	INORG	Sodium	605		mg/kg		B	SOIL	TRENCH 1 #4	3.5	6/2/97
4CN04301C1	INORG	Sodium	4470		mg/kg			SOIL	TRENCH 2 #1	3.5	6/2/97
4CN03501C1	INORG	Sodium	3690		mg/kg			SOIL	TRENCH 1 #1	4	6/2/97
4CN03701C1	INORG	Sodium	324		mg/kg		B	SOIL	TRENCH 1 #3	4	6/2/97
4CN03601C1	INORG	Sodium	2760		mg/kg			SOIL	TRENCH 1 #2	4.5	6/2/97
4CN03602C1	INORG	Sodium	2670		mg/kg			SOIL	TRENCH 1 #2	4.5	6/2/97
4CN05101C1	INORG	Sodium	1260		mg/kg			SOIL	TRENCH 3 #1	5.6	6/2/97
4CN05201C1	INORG	Sodium	716		mg/kg		B	SOIL	TRENCH 3 #2	6	6/2/97
4CN05401C1	INORG	Sodium	2650		mg/kg			SOIL	TRENCH 3 #4	6.5	6/2/97
4CN05301C1	INORG	Sodium	3850		mg/kg			SOIL	TRENCH 3 #3	6.8	6/2/97
4CN04601C1	INORG	Sodium	1210		mg/kg			SOIL	TRENCH 2 #4	7	6/2/97
4CN04501C1	INORG	Sodium	1770		mg/kg			SOIL	TRENCH 2 #3	7.5	6/2/97
4CN04401C1	INORG	Sodium	3810		mg/kg			SOIL	TRENCH 2 #2	8	6/2/97

Sample no.	Analysis	Compound	Conc	Rad uncrt	Units	Q flags	Matrix	Type location	Depth (ft)	Sample date
40400101U9	RAD	Sr-90	1.1	0.20	pCi/g	J	SOIL	INLET 1	0-0.5	7/18/95
40400301U9	RAD	Sr-90	6.3	0.40	pCi/g	J	SOIL	INLET 2	0-0.5	7/18/95
40400501U9	RAD	Sr-90	3.7	0.50	pCi/g	J	SOIL	INLET 3	0-0.5	7/18/95
40400701U9	RAD	Sr-90	5	0.50	pCi/g	J	SOIL	INLET 4	0-0.5	7/18/95
40400201U9	RAD	Sr-90	2.8	0.30	pCi/g	J	SOIL	INLET 2	0.17-0.67	7/18/95
40400202U9	RAD	Sr-90	3.7	0.30	pCi/g	J	SOIL	INLET 2	0.17-0.67	7/18/95
HG522901F7	RAD	Sr-90	0.888	0.08	pCi/g	J	SOIL	SA 47	0-1	10/9/97
HG522201F7	RAD	Sr-90	0.847	0.07	pCi/g	J	SOIL	SA 40	0-1	10/9/97
HG521601F7	RAD	Sr-90	0.819	0.08	pCi/g	J	SOIL	SA 34	0-1	10/9/97
HG522701F7	RAD	Sr-90	0.743	0.08	pCi/g	J	SOIL	SA 45	0-1	10/9/97
HG521301F7	RAD	Sr-90	0.695	0.07	pCi/g	J	SOIL	SA 31	0-1	10/9/97
HG521401F7	RAD	Sr-90	0.672	0.08	pCi/g	J	SOIL	SA 32	0-1	10/9/97
HG522101F7	RAD	Sr-90	0.634	0.06	pCi/g	J	SOIL	SA 39	0-1	10/9/97
HG521901F7	RAD	Sr-90	0.63	0.07	pCi/g	J	SOIL	SA 37	0-1	10/9/97
HG522102F7	RAD	Sr-90	0.598	0.09	pCi/g	J	SOIL	SA 39	0-1	10/9/97
HG521801F7	RAD	Sr-90	0.588	0.06	pCi/g	J	SOIL	SA 36	0-1	10/9/97
HG522801F7	RAD	Sr-90	0.582	0.07	pCi/g	J	SOIL	SA 46	0-1	10/9/97
HG521701F7	RAD	Sr-90	0.572	0.07	pCi/g	J	SOIL	SA 36	0-1	10/9/97
HG522301F7	RAD	Sr-90	0.571	0.07	pCi/g	J	SOIL	SA 41	0-1	10/9/97
HG521201F7	RAD	Sr-90	0.558	0.06	pCi/g	J	SOIL	SA 30	0-1	10/9/97
HG522001F7	RAD	Sr-90	0.539	0.06	pCi/g	J	SOIL	SA 38	0-1	10/9/97
HG522401F7	RAD	Sr-90	0.534	0.06	pCi/g	J	SOIL	SA 42	0-1	10/9/97
HG521501F7	RAD	Sr-90	0.493	0.06	pCi/g	UJ	SOIL	SA 33	0-1	10/9/97
HG520201F7	RAD	Sr-90	0.452	0.08	pCi/g	UJ	SOIL	SA 20	0-1	10/8/97
HG520102F7	RAD	Sr-90	0.435	0.08	pCi/g	UJ	SOIL	SA 19	0-1	10/8/97
HG520401F7	RAD	Sr-90	0.428	0.09	pCi/g	UJ	SOIL	SA 22	0-1	10/8/97
HG520901F7	RAD	Sr-90	0.413	0.11	pCi/g	UJ	SOIL	SA 27	0-1	10/8/97
HG522601F7	RAD	Sr-90	0.379	0.06	pCi/g	UJ	SOIL	SA 44	0-1	10/9/97
HG522501F7	RAD	Sr-90	0.357	0.07	pCi/g	UJ	SOIL	SA 43	0-1	10/9/97
HG520101F7	RAD	Sr-90	0.352	0.06	pCi/g	UJ	SOIL	SA 19	0-1	10/8/97
HG520601F7	RAD	Sr-90	0.336	0.08	pCi/g	UJ	SOIL	SA 24	0-1	10/8/97
HG521001F7	RAD	Sr-90	0.311	0.08	pCi/g	UJ	SOIL	SA 28	0-1	10/8/97
HG520701F7	RAD	Sr-90	0.305	0.06	pCi/g	UJ	SOIL	SA 25	0-1	10/8/97
HG520001F7	RAD	Sr-90	0.286	0.09	pCi/g	UJ	SOIL	SA 18	0-1	10/8/97
HG520301F7	RAD	Sr-90	0.284	0.07	pCi/g	UJ	SOIL	SA 21	0-1	10/8/97
HG520801F7	RAD	Sr-90	0.246	0.08	pCi/g	UJ	SOIL	SA 26	0-1	10/8/97
HG521101F7	RAD	Sr-90	0.229	0.08	pCi/g	UJ	SOIL	SA 29	0-1	10/8/97
HG520501F7	RAD	Sr-90	0.13	0.04	pCi/g	UJ	SOIL	SA 23	0-1	10/8/97
40400401U9	RAD	Sr-90	4.7	0.50	pCi/g	J	SOIL	INLET 2	1.5	7/18/95
40400601U9	RAD	Sr-90	6.2	0.80	pCi/g	J	SOIL	INLET 3	1.5	7/18/95
40400801U9	RAD	Sr-90	4.1	0.60	pCi/g	J	SOIL	INLET 4	1.5	7/18/95
40400201CV	VOAS - CLP	Styrene	10		ug/kg	U	SOIL	INLET 2	0.17-0.67	7/18/95
40400202CV	VOAS - CLP	Styrene	12		ug/kg	U	SOIL	INLET 2	0.17-0.67	7/18/95
40400401CV	VOAS - CLP	Styrene	11		ug/kg	U	SOIL	INLET 2	0.17-0.67	7/18/95
40400601CV	VOAS - CLP	Styrene	12		ug/kg	U	SOIL	INLET 3	1.5	7/18/95
40400801CV	VOAS - CLP	Styrene	12		ug/kg	U	SOIL	INLET 4	1.5	7/18/95
4CN03801VG	VOAS - CLP	Styrene	11		ug/kg	U	SOIL	TRENCH 1 #4	3.5	6/2/97
4CN04301VG	VOAS - CLP	Styrene	12		ug/kg	U	SOIL	TRENCH 2 #1	3.5	6/2/97
4CN03501VG	VOAS - CLP	Styrene	12		ug/kg	U	SOIL	TRENCH 1 #1	4	6/2/97
4CN03701VG	VOAS - CLP	Styrene	11		ug/kg	U	SOIL	TRENCH 1 #3	4	6/2/97
4CN03601VG	VOAS - CLP	Styrene	12		ug/kg	U	SOIL	TRENCH 1 #2	4.5	6/2/97
4CN03602VG	VOAS - CLP	Styrene	12		ug/kg	U	SOIL	TRENCH 1 #2	4.5	6/2/97
4CN05101VG	VOAS - CLP	Styrene	11		ug/kg	U	SOIL	TRENCH 3 #1	5.6	6/2/97
4CN05201VG	VOAS - CLP	Styrene	12		ug/kg	U	SOIL	TRENCH 3 #2	6	6/2/97
4CN05401VG	VOAS - CLP	Styrene	12		ug/kg	U	SOIL	TRENCH 3 #4	6.5	6/2/97
4CN05301VG	VOAS - CLP	Styrene	12		ug/kg	U	SOIL	TRENCH 3 #3	6.8	6/2/97
4CN04601VG	VOAS - CLP	Styrene	11		ug/kg	U	SOIL	TRENCH 2 #4	7	6/2/97
4CN04501VG	VOAS - CLP	Styrene	12		ug/kg	U	SOIL	TRENCH 2 #3	7.5	6/2/97
4CN04401VG	VOAS - CLP	Styrene	12		ug/kg	U	SOIL	TRENCH 2 #2	8	6/2/97
40400201CV	VOAS - CLP	Tetrachloroethene	10		ug/kg	U	SOIL	INLET 2	0.17-0.67	7/18/95
40400202CV	VOAS - CLP	Tetrachloroethene	12		ug/kg	U	SOIL	INLET 2	0.17-0.67	7/18/95

Sample no.	Analysis	Compound	Conc	Rad uncrt	Units	Q flags	Matrix	Type location	Depth (ft)	Sample date
40400401CV	VOAS - CLP	Tetrachloroethene	11		ug/kg	U	SOIL	INLET 2	0.17-0.67	7/18/95
40400601CV	VOAS - CLP	Tetrachloroethene	12		ug/kg	U	SOIL	INLET 3	1.5	7/18/95
40400801CV	VOAS - CLP	Tetrachloroethene	12		ug/kg	U	SOIL	INLET 4	1.5	7/18/95
4CN03801VG	VOAS - CLP	Tetrachloroethene	11		ug/kg	U	SOIL	TRENCH 1 #4	3.5	6/2/97
4CN04301TV	VOAS - TCLP	Tetrachloroethene	25		ug/L	U	WATER	TRENCH 2 #1	3.5	6/2/97
4CN04301VG	VOAS - CLP	Tetrachloroethene	12		ug/kg	U	SOIL	TRENCH 2 #1	3.5	6/2/97
4CN03501VG	VOAS - CLP	Tetrachloroethene	12		ug/kg	U	SOIL	TRENCH 1 #1	4	6/2/97
4CN03701VG	VOAS - CLP	Tetrachloroethene	11		ug/kg	U	SOIL	TRENCH 1 #3	4	6/2/97
4CN03601VG	VOAS - CLP	Tetrachloroethene	12		ug/kg	U	SOIL	TRENCH 1 #2	4.5	6/2/97
4CN03602VG	VOAS - CLP	Tetrachloroethene	12		ug/kg	U	SOIL	TRENCH 1 #2	4.5	6/2/97
4CN05101TV	VOAS - TCLP	Tetrachloroethene	25		ug/L	U	WATER	TRENCH 3 #1	5.6	6/2/97
4CN05101VG	VOAS - CLP	Tetrachloroethene	11		ug/kg	U	SOIL	TRENCH 3 #1	5.6	6/2/97
4CN05201VG	VOAS - CLP	Tetrachloroethene	12		ug/kg	U	SOIL	TRENCH 3 #2	6	6/2/97
4CN05401VG	VOAS - CLP	Tetrachloroethene	12		ug/kg	U	SOIL	TRENCH 3 #4	6.5	6/2/97
4CN05301VG	VOAS - CLP	Tetrachloroethene	12		ug/kg	U	SOIL	TRENCH 3 #3	6.8	6/2/97
4CN04601VG	VOAS - CLP	Tetrachloroethene	11		ug/kg	U	SOIL	TRENCH 2 #4	7	6/2/97
4CN04501VG	VOAS - CLP	Tetrachloroethene	12		ug/kg	U	SOIL	TRENCH 2 #3	7.5	6/2/97
4CN04401VG	VOAS - CLP	Tetrachloroethene	12		ug/kg	U	SOIL	TRENCH 2 #2	8	6/2/97
40400101R4	RAD	Th-234	16.3	1.60	pCi/g		SUR	INLET 1	0-0.5	7/18/95
40400501R4	RAD	Th-234	7.5	1.20	pCi/g		SUR	INLET 3	0-0.5	7/18/95
40400701R4	RAD	Th-234	16.9	1.60	pCi/g		SUR	INLET 4	0-0.5	7/18/95
40400201R4	RAD	Th-234	41	6.00	pCi/g		SUR	INLET 2	0.17-0.67	7/18/95
40400202R4	RAD	Th-234	48	7.00	pCi/g		SUR	INLET 2	0.17-0.67	7/18/95
40400601R4	RAD	Th-234	7	1.10	pCi/g		SUR	INLET 3	1.5	7/18/95
40400101C1	INORG	Thallium	0.7		mg/kg	U	SOIL	INLET 1	0-0.5	7/18/95
40400301C1	INORG	Thallium	0.61		mg/kg	U	SOIL	INLET 2	0-0.5	7/18/95
40400501C1	INORG	Thallium	0.63		mg/kg	U	SOIL	INLET 3	0-0.5	7/18/95
40400701C1	INORG	Thallium	0.62		mg/kg	U	SOIL	INLET 4	0-0.5	7/18/95
4CC03501LM	INORG	Thallium	0.19		mg/kg	U	SOIL	POND 32	0-0.5	7/16/97
4CC03601LM	INORG	Thallium	0.2		mg/kg	B	SOIL	POND 33	0-0.5	7/16/97
4CC03701LM	INORG	Thallium	0.25		mg/kg	B	SOIL	POND 34	0-0.5	7/16/97
4CC03801LM	INORG	Thallium	0.31		mg/kg	B	SOIL	POND 35	0-0.5	7/16/97
4CC03901LM	INORG	Thallium	0.24		mg/kg	B	SOIL	POND 36	0-0.5	7/16/97
4CC04001LM	INORG	Thallium	0.2		mg/kg	U	SOIL	POND 37	0-0.5	7/16/97
4CC04002LM	INORG	Thallium	0.2		mg/kg	U	SOIL	POND 37	0-0.5	7/16/97
40400201C1	INORG	Thallium	0.63		mg/kg	U	SOIL	INLET 2	0.17-0.67	7/18/95
40400202C1	INORG	Thallium	0.7		mg/kg	U	SOIL	INLET 2	0.17-0.67	7/18/95
40400401C1	INORG	Thallium	0.64		mg/kg	U	SOIL	INLET 2	0.17-0.67	7/18/95
HG522601C1	INORG	Thallium	0.41		mg/kg	U P	SOIL	SA 44	0-1	10/9/97
HG523001C1	INORG	Thallium	0.41		mg/kg	U P	SOIL	SA 48	0-1	10/9/97
HG522501C1	INORG	Thallium	0.4		mg/kg	U P	SOIL	SA 43	0-1	10/9/97
HG522102C1	INORG	Thallium	0.39		mg/kg	U P	SOIL	SA 39	0-1	10/9/97
HG520301C1	INORG	Thallium	0.38		mg/kg	U P	SOIL	SA 21	0-1	10/8/97
HG521801C1	INORG	Thallium	0.38		mg/kg	U P	SOIL	SA 36	0-1	10/9/97
HG522901C1	INORG	Thallium	0.37		mg/kg	U P	SOIL	SA 47	0-1	10/9/97
HG523101C1	INORG	Thallium	0.37		mg/kg	U P	SOIL	SA 49	0-1	10/9/97
HG520101C1	INORG	Thallium	0.37		mg/kg	U P	SOIL	SA 19	0-1	10/8/97
HG521901C1	INORG	Thallium	0.37		mg/kg	U P	SOIL	SA 37	0-1	10/9/97
HG522801C1	INORG	Thallium	0.36		mg/kg	U P	SOIL	SA 46	0-1	10/9/97
HG521101C1	INORG	Thallium	0.36		mg/kg	U P	SOIL	SA 29	0-1	10/8/97
HG521301C1	INORG	Thallium	0.36		mg/kg	U P	SOIL	SA 31	0-1	10/9/97
HG521001C1	INORG	Thallium	0.35		mg/kg	U P	SOIL	SA 28	0-1	10/8/97
HG523501C1	INORG	Thallium	0.35		mg/kg	NUJ P	SOIL	SA 53	0-1	10/13/97
HG524201C1	INORG	Thallium	0.35		mg/kg	NUJ P	SOIL	SA 60	0-1	10/13/97
HG520201C1	INORG	Thallium	0.35		mg/kg	U P	SOIL	SA 20	0-1	10/8/97
HG520601C1	INORG	Thallium	0.34		mg/kg	U P	SOIL	SA 24	0-1	10/8/97
HG522401C1	INORG	Thallium	0.34		mg/kg	U P	SOIL	SA 42	0-1	10/9/97
HG522701C1	INORG	Thallium	0.34		mg/kg	U P	SOIL	SA 45	0-1	10/9/97
HG523601C1	INORG	Thallium	0.34		mg/kg	NUJ P	SOIL	SA 54	0-1	10/13/97
HG520901C1	INORG	Thallium	0.34		mg/kg	U P	SOIL	SA 27	0-1	10/8/97
HG521401C1	INORG	Thallium	0.34		mg/kg	U P	SOIL	SA 32	0-1	10/9/97

Sample no.	Analysis	Compound	Conc	Rad uncrt	Units	Q flags	Matrix	Type location	Depth (ft)	Sample date
HG521201C1	INORG	Thallium	0.33		mg/kg	U P	SOIL	SA 30	0-1	10/9/97
HG523701C1	INORG	Thallium	0.33		mg/kg	NUJ P	SOIL	SA 55	0-1	10/13/97
HG524102C1	INORG	Thallium	0.33		mg/kg	NUJ P	SOIL	SA 59	0-1	10/13/97
HG522001C1	INORG	Thallium	0.33		mg/kg	U P	SOIL	SA 38	0-1	10/9/97
HG520102C1	INORG	Thallium	0.33		mg/kg	U P	SOIL	SA 19	0-1	10/8/97
HG520801C1	INORG	Thallium	0.33		mg/kg	U P	SOIL	SA 26	0-1	10/8/97
HG520701C1	INORG	Thallium	0.33		mg/kg	U P	SOIL	SA 25	0-1	10/8/97
HG520501C1	INORG	Thallium	0.33		mg/kg	U P	SOIL	SA 23	0-1	10/8/97
HG524101C1	INORG	Thallium	0.32		mg/kg	NUJ P	SOIL	SA 59	0-1	10/13/97
HG523201C1	INORG	Thallium	0.31		mg/kg	NUJ P	SOIL	SA 50	0-1	10/13/97
HG523401C1	INORG	Thallium	0.31		mg/kg	NUJ P	SOIL	SA 52	0-1	10/13/97
HG521701C1	INORG	Thallium	0.31		mg/kg	U P	SOIL	SA 36	0-1	10/9/97
HG520001C1	INORG	Thallium	0.31		mg/kg	U P	SOIL	SA 18	0-1	10/8/97
HG520401C1	INORG	Thallium	0.31		mg/kg	U P	SOIL	SA 22	0-1	10/8/97
HG522101C1	INORG	Thallium	0.3		mg/kg	U P	SOIL	SA 39	0-1	10/9/97
HG521601C1	INORG	Thallium	0.3		mg/kg	U P	SOIL	SA 34	0-1	10/9/97
HG523801C1	INORG	Thallium	0.3		mg/kg	NUJ P	SOIL	SA 56	0-1	10/13/97
HG524301C1	INORG	Thallium	0.3		mg/kg	NUJ P	SOIL	SA 61	0-1	10/13/97
HG524401C1	INORG	Thallium	0.3		mg/kg	NUJ P	SOIL	SA 62	0-1	10/13/97
HG523901C1	INORG	Thallium	0.29		mg/kg	NUJ P	SOIL	SA 57	0-1	10/13/97
HG524001C1	INORG	Thallium	0.29		mg/kg	NUJ P	SOIL	SA 57	0-1	10/13/97
HG521501C1	INORG	Thallium	0.29		mg/kg	U P	SOIL	SA 33	0-1	10/9/97
HG522201C1	INORG	Thallium	0.29		mg/kg	U P	SOIL	SA 40	0-1	10/9/97
HG522301C1	INORG	Thallium	0.28		mg/kg	U P	SOIL	SA 41	0-1	10/9/97
HG523301C1	INORG	Thallium	0.28		mg/kg	NUJ P	SOIL	SA 51	0-1	10/13/97
HG523801N2	INORG	Thallium	0.28		mg/kg	NUJ P	SOIL	SA 56	0-1	10/13/97
40400601C1	INORG	Thallium	0.72		mg/kg	U	SOIL	INLET 3	1.5	7/18/95
40400801C1	INORG	Thallium	0.74		mg/kg	U	SOIL	INLET 4	1.5	7/18/95
4CN03801C1	INORG	Thallium	0.16		mg/kg	UJ	SOIL	TRENCH 1 #4	3.5	6/2/97
4CN04301C1	INORG	Thallium	0.18		mg/kg	WUJ	SOIL	TRENCH 2 #1	3.5	6/2/97
4CN03501C1	INORG	Thallium	0.19		mg/kg	WUJ	SOIL	TRENCH 1 #1	4	6/2/97
4CN03701C1	INORG	Thallium	0.17		mg/kg	UJ	SOIL	TRENCH 1 #3	4	6/2/97
4CN03601C1	INORG	Thallium	0.18		mg/kg	UJ	SOIL	TRENCH 1 #2	4.5	6/2/97
4CN03602C1	INORG	Thallium	0.18		mg/kg	UJ	SOIL	TRENCH 1 #2	4.5	6/2/97
4CN05101C1	INORG	Thallium	0.17		mg/kg	UJ	SOIL	TRENCH 3 #1	5.6	6/2/97
4CN05201C1	INORG	Thallium	0.15		mg/kg	UJ	SOIL	TRENCH 3 #2	6	6/2/97
4CN05401C1	INORG	Thallium	0.18		mg/kg	UJ	SOIL	TRENCH 3 #4	6.5	6/2/97
4CN05301C1	INORG	Thallium	0.18		mg/kg	UJ	SOIL	TRENCH 3 #3	6.8	6/2/97
4CN04601C1	INORG	Thallium	0.16		mg/kg	UJ	SOIL	TRENCH 2 #4	7	6/2/97
4CN04501C1	INORG	Thallium	0.18		mg/kg	UJ	SOIL	TRENCH 2 #3	7.5	6/2/97
4CN04401C1	INORG	Thallium	0.18		mg/kg	UJ	SOIL	TRENCH 2 #2	8	6/2/97
40400201CV	VOAS - CLP	Toluene	10		ug/kg	U	SOIL	INLET 2	0.17-0.67	7/18/95
40400202CV	VOAS - CLP	Toluene	12		ug/kg	U	SOIL	INLET 2	0.17-0.67	7/18/95
40400401CV	VOAS - CLP	Toluene	11		ug/kg	U	SOIL	INLET 2	0.17-0.67	7/18/95
40400601CV	VOAS - CLP	Toluene	12		ug/kg	U	SOIL	INLET 3	1.5	7/18/95
40400801CV	VOAS - CLP	Toluene	12		ug/kg	U	SOIL	INLET 4	1.5	7/18/95
4CN03801VG	VOAS - CLP	Toluene	1		ug/kg	J	SOIL	TRENCH 1 #4	3.5	6/2/97
4CN04301VG	VOAS - CLP	Toluene	12		ug/kg	U	SOIL	TRENCH 2 #1	3.5	6/2/97
4CN03501VG	VOAS - CLP	Toluene	12		ug/kg	U	SOIL	TRENCH 1 #1	4	6/2/97
4CN03701VG	VOAS - CLP	Toluene	11		ug/kg	U	SOIL	TRENCH 1 #3	4	6/2/97
4CN03601VG	VOAS - CLP	Toluene	12		ug/kg	U	SOIL	TRENCH 1 #2	4.5	6/2/97
4CN03602VG	VOAS - CLP	Toluene	12		ug/kg	U	SOIL	TRENCH 1 #2	4.5	6/2/97
4CN05101VG	VOAS - CLP	Toluene	1		ug/kg	J	SOIL	TRENCH 3 #1	5.6	6/2/97
4CN05201VG	VOAS - CLP	Toluene	12		ug/kg	U	SOIL	TRENCH 3 #2	6	6/2/97
4CN05401VG	VOAS - CLP	Toluene	1		ug/kg	J	SOIL	TRENCH 3 #4	6.5	6/2/97
4CN05301VG	VOAS - CLP	Toluene	12		ug/kg	U	SOIL	TRENCH 3 #3	6.8	6/2/97
4CN04601VG	VOAS - CLP	Toluene	11		ug/kg	U	SOIL	TRENCH 2 #4	7	6/2/97
4CN04501VG	VOAS - CLP	Toluene	12		ug/kg	U	SOIL	TRENCH 2 #3	7.5	6/2/97
4CN04401VG	VOAS - CLP	Toluene	1		ug/kg	J	SOIL	TRENCH 2 #2	8	6/2/97
40400201CV	VOAS - CLP	Trichloroethene	10		ug/kg	U	SOIL	INLET 2	0.17-0.67	7/18/95
40400202CV	VOAS - CLP	Trichloroethene	12		ug/kg	U	SOIL	INLET 2	0.17-0.67	7/18/95

Sample no.	Analysis	Compound	Conc	Rad uncrt	Units	Q flags	Matrix	Type location	Depth (ft)	Sample date
40400401CV	VOAS - CLP	Trichloroethene	11		ug/kg	U	SOIL	INLET 2	0.17-0.67	7/18/95
40400601CV	VOAS - CLP	Trichloroethene	12		ug/kg	U	SOIL	INLET 3	1.5	7/18/95
40400801CV	VOAS - CLP	Trichloroethene	12		ug/kg	U	SOIL	INLET 4	1.5	7/18/95
4CN03801VG	VOAS - CLP	Trichloroethene	11		ug/kg	U	SOIL	TRENCH 1 #4	3.5	6/2/97
4CN04301TV	VOAS - TCLP	Trichloroethene	25		ug/L	U	WATER	TRENCH 2 #1	3.5	6/2/97
4CN04301VG	VOAS - CLP	Trichloroethene	12		ug/kg	U	SOIL	TRENCH 2 #1	3.5	6/2/97
4CN03501VG	VOAS - CLP	Trichloroethene	12		ug/kg	U	SOIL	TRENCH 1 #1	4	6/2/97
4CN03701VG	VOAS - CLP	Trichloroethene	11		ug/kg	U	SOIL	TRENCH 1 #3	4	6/2/97
4CN03601VG	VOAS - CLP	Trichloroethene	12		ug/kg	U	SOIL	TRENCH 1 #2	4.5	6/2/97
4CN03602VG	VOAS - CLP	Trichloroethene	12		ug/kg	U	SOIL	TRENCH 1 #2	4.5	6/2/97
4CN05101TV	VOAS - TCLP	Trichloroethene	25		ug/L	U	WATER	TRENCH 3 #1	5.6	6/2/97
4CN05101VG	VOAS - CLP	Trichloroethene	11		ug/kg	U	SOIL	TRENCH 3 #1	5.6	6/2/97
4CN05201VG	VOAS - CLP	Trichloroethene	12		ug/kg	U	SOIL	TRENCH 3 #2	6	6/2/97
4CN05401VG	VOAS - CLP	Trichloroethene	12		ug/kg	U	SOIL	TRENCH 3 #4	6.5	6/2/97
4CN05301VG	VOAS - CLP	Trichloroethene	12		ug/kg	U	SOIL	TRENCH 3 #3	6.8	6/2/97
4CN04601VG	VOAS - CLP	Trichloroethene	11		ug/kg	U	SOIL	TRENCH 2 #4	7	6/2/97
4CN04501VG	VOAS - CLP	Trichloroethene	12		ug/kg	U	SOIL	TRENCH 2 #3	7.5	6/2/97
4CN04401VG	VOAS - CLP	Trichloroethene	12		ug/kg	U	SOIL	TRENCH 2 #2	8	6/2/97
40400101U9	RAD	U-234	7.4	0.50	pCi/g		SOIL	INLET 1	0-0.5	7/18/95
40400301U9	RAD	U-234	1.55	0.11	pCi/g		SOIL	INLET 2	0-0.5	7/18/95
40400501U9	RAD	U-234	5.3	0.40	pCi/g		SOIL	INLET 3	0-0.5	7/18/95
40400701U9	RAD	U-234	9.6	0.90	pCi/g		SOIL	INLET 4	0-0.5	7/18/95
4CC00201R9	RAD	U-234	0.884	0.07	pCi/g		MSOIL	POND 2	0-0.5	5/14/97
4CC00501R9	RAD	U-234	0.779	0.07	pCi/g		MSOIL	POND 4	0-0.5	5/14/97
4CC00801R9	RAD	U-234	0.657	0.06	pCi/g		MSOIL	POND 7	0-0.5	5/14/97
4CC00901R9	RAD	U-234	0.833	0.07	pCi/g		MSOIL	POND 8	0-0.5	5/14/97
4CC01001R9	RAD	U-234	0.925	0.08	pCi/g		MSOIL	POND 9	0-0.5	5/14/97
4CC01301R9	RAD	U-234	1.05	0.08	pCi/g		MSOIL	POND 11	0-0.5	5/14/97
4CC01701R9	RAD	U-234	0.887	0.08	pCi/g		MSOIL	POND 15	0-0.5	5/14/97
4CC01901R9	RAD	U-234	0.926	0.07	pCi/g		MSOIL	POND 16	0-0.5	5/14/97
4CC02201R9	RAD	U-234	0.876	0.07	pCi/g		MSOIL	POND 19	0-0.5	5/14/97
4CC02501R9	RAD	U-234	0.921	0.08	pCi/g		MSOIL	POND 22	0-0.5	5/14/97
4CC02601R9	RAD	U-234	0.876	0.07	pCi/g		MSOIL	POND 23	0-0.5	5/14/97
4CC02602R9	RAD	U-234	0.675	0.06	pCi/g		MSOIL	POND 23	0-0.5	5/14/97
4CC02701R9	RAD	U-234	1.26	0.10	pCi/g		MSOIL	POND 24	0-0.5	5/14/97
4CC02901R9	RAD	U-234	0.915	0.08	pCi/g		MSOIL	POND 26	0-0.5	5/14/97
4CC03101R9	RAD	U-234	0.762	0.06	pCi/g		MSOIL	POND 28	0-0.5	5/14/97
4CC03301R9	RAD	U-234	0.749	0.06	pCi/g		MSOIL	POND 30	0-0.5	5/14/97
40400201U9	RAD	U-234	19.4	1.20	pCi/g		SOIL	INLET 2	0.17-0.67	7/18/95
40400202U9	RAD	U-234	22.6	1.40	pCi/g		SOIL	INLET 2	0.17-0.67	7/18/95
40400401U9	RAD	U-234	1.83	0.14	pCi/g		SOIL	INLET 2	1.5	7/18/95
40400601U9	RAD	U-234	3.1	0.20	pCi/g		SOIL	INLET 3	1.5	7/18/95
40400801U9	RAD	U-234	1.7	0.20	pCi/g		SOIL	INLET 4	1.5	7/18/95
4CC01801R9	RAD	U-234	1.18	0.09	pCi/g		MSOIL	POND 15	2-4	5/14/97
4CP06101R9	RAD	U-234	1.4	0.11	pCi/g		MSOIL	PIPE 2	2-4	5/14/97
4CC01101R9	RAD	U-234	1.25	0.10	pCi/g		MSOIL	POND 9	3-5	5/14/97
4CN03801R9	RAD	U-234	0.794	0.06	pCi/g		MSOIL	TRENCH 1 #4	3.5	6/2/97
4CN04301R9	RAD	U-234	1.97	0.13	pCi/g		MSOIL	TRENCH 2 #1	3.5	6/2/97
4CC00301R9	RAD	U-234	2.85	0.19	pCi/g		MSOIL	POND 2	3.5-5.5	5/14/97
4CN03501R9	RAD	U-234	1.51	0.11	pCi/g		MSOIL	TRENCH 1 #1	4	6/2/97
4CN03701R9	RAD	U-234	0.745	0.06	pCi/g		MSOIL	TRENCH 1 #3	4	6/2/97
4CN03601R9	RAD	U-234	1.33	0.10	pCi/g		MSOIL	TRENCH 1 #2	4.5	6/2/97
4CN03602R9	RAD	U-234	1.29	0.09	pCi/g		MSOIL	TRENCH 1 #2	4.5	6/2/97
4CP05901R9	RAD	U-234	1.82	0.13	pCi/g		MSOIL	PIPE 1	5-7	5/14/97
4CP06001R9	RAD	U-234	2.45	0.17	pCi/g		MSOIL	PIPE 2	5-7	5/14/97
4CP06201R9	RAD	U-234	1.8	0.13	pCi/g		MSOIL	PIPE 3	5-7	5/14/97
4CP06301R9	RAD	U-234	1.44	0.11	pCi/g		MSOIL	PIPE 4	5-7	5/14/97
4CN05101R9	RAD	U-234	0.799	0.07	pCi/g		MSOIL	TRENCH 3 #1	5.6	6/2/97
4CN05201R9	RAD	U-234	0.651	0.05	pCi/g		MSOIL	TRENCH 3 #2	6	6/2/97
4CN05401R9	RAD	U-234	1.83	0.13	pCi/g		MSOIL	TRENCH 3 #4	6.5	6/2/97
4CN05301R9	RAD	U-234	1.58	0.11	pCi/g		MSOIL	TRENCH 3 #3	6.8	6/2/97

Sample no.	Analysis	Compound	Conc	Rad uncrt	Units	Q flags	Matrix	Type location	Depth (ft)	Sample date
4CN04601R9	RAD	U-234	0.764	0.06	pCi/g		MSOIL	TRENCH 2 #4	7	6/2/97
4CN04501R9	RAD	U-234	0.932	0.07	pCi/g		MSOIL	TRENCH 2 #3	7.5	6/2/97
4CN04401R9	RAD	U-234	1.37	0.10	pCi/g		MSOIL	TRENCH 2 #2	8	6/2/97
HG520501R9	RAD	U-233/234	1.04	0.27	pCi/g		SOIL	SA 23	0-1	10/8/97
HG520901R9	RAD	U-233/234	0.951	0.25	pCi/g		SOIL	SA 27	0-1	10/8/97
HG520401R9	RAD	U-233/234	0.938	0.25	pCi/g		SOIL	SA 22	0-1	10/8/97
HG521001R9	RAD	U-233/234	0.924	0.25	pCi/g		SOIL	SA 28	0-1	10/8/97
HG522501R9	RAD	U-233/234	0.899	0.24	pCi/g		SOIL	SA 43	0-1	10/9/97
HG520601R9	RAD	U-233/234	0.894	0.24	pCi/g		SOIL	SA 24	0-1	10/8/97
HG522101R9	RAD	U-233/234	0.886	0.24	pCi/g		SOIL	SA 39	0-1	10/9/97
HG521501R9	RAD	U-233/234	0.88	0.24	pCi/g		SOIL	SA 33	0-1	10/9/97
HG520701R9	RAD	U-233/234	0.879	0.24	pCi/g		SOIL	SA 25	0-1	10/8/97
HG522401R9	RAD	U-233/234	0.869	0.23	pCi/g		SOIL	SA 42	0-1	10/9/97
HG520801R9	RAD	U-233/234	0.86	0.23	pCi/g		SOIL	SA 26	0-1	10/8/97
HG521301R9	RAD	U-233/234	0.846	0.23	pCi/g		SOIL	SA 31	0-1	10/9/97
HG520001R9	RAD	U-233/234	0.84	0.22	pCi/g		SOIL	SA 18	0-1	10/8/97
HG522901R9	RAD	U-233/234	0.831	0.22	pCi/g		SOIL	SA 47	0-1	10/9/97
HG522301R9	RAD	U-233/234	0.829	0.22	pCi/g		SOIL	SA 41	0-1	10/9/97
HG522001R9	RAD	U-233/234	0.82	0.22	pCi/g		SOIL	SA 38	0-1	10/9/97
HG522601R9	RAD	U-233/234	0.816	0.22	pCi/g		SOIL	SA 44	0-1	10/9/97
HG520201R9	RAD	U-233/234	0.816	0.22	pCi/g		SOIL	SA 20	0-1	10/8/97
HG521101R9	RAD	U-233/234	0.813	0.22	pCi/g		SOIL	SA 29	0-1	10/8/97
HG522801R9	RAD	U-233/234	0.796	0.21	pCi/g		SOIL	SA 46	0-1	10/9/97
HG521201R9	RAD	U-233/234	0.791	0.21	pCi/g		SOIL	SA 30	0-1	10/9/97
HG521401R9	RAD	U-233/234	0.789	0.21	pCi/g		SOIL	SA 32	0-1	10/9/97
HG522701R9	RAD	U-233/234	0.78	0.21	pCi/g		SOIL	SA 45	0-1	10/9/97
HG521701R9	RAD	U-233/234	0.779	0.21	pCi/g		SOIL	SA 36	0-1	10/9/97
HG521901R9	RAD	U-233/234	0.771	0.21	pCi/g		SOIL	SA 37	0-1	10/9/97
HG520301R9	RAD	U-233/234	0.768	0.21	pCi/g		SOIL	SA 21	0-1	10/8/97
HG520102R9	RAD	U-233/234	0.765	0.20	pCi/g		SOIL	SA 19	0-1	10/8/97
HG522102R9	RAD	U-233/234	0.752	0.20	pCi/g		SOIL	SA 39	0-1	10/9/97
HG521601R9	RAD	U-233/234	0.738	0.20	pCi/g		SOIL	SA 34	0-1	10/9/97
HG521801R9	RAD	U-233/234	0.727	0.20	pCi/g		SOIL	SA 36	0-1	10/9/97
HG522201R9	RAD	U-233/234	0.72	0.19	pCi/g		SOIL	SA 40	0-1	10/9/97
HG520101R9	RAD	U-233/234	0.698	0.19	pCi/g		SOIL	SA 19	0-1	10/8/97
40400101R4	RAD	U-235	0.6	0.06	pCi/g		SUR	INLET 1	0-0.5	7/18/95
40400101U9	RAD	U-235	0.32	0.04	pCi/g		SOIL	INLET 1	0-0.5	7/18/95
40400301U9	RAD	U-235	0.075	0.02	pCi/g		SOIL	INLET 2	0-0.5	7/18/95
40400501R4	RAD	U-235	0.38	0.15	pCi/g		SUR	INLET 3	0-0.5	7/18/95
40400501U9	RAD	U-235	0.2	0.03	pCi/g		SOIL	INLET 3	0-0.5	7/18/95
40400701R4	RAD	U-235	0.64	0.06	pCi/g		SUR	INLET 4	0-0.5	7/18/95
40400701U9	RAD	U-235	0.62	0.08	pCi/g		SOIL	INLET 4	0-0.5	7/18/95
4CC00201R9	RAD	U-235	0.0286	0.01	pCi/g		MSOIL	POND 2	0-0.5	5/14/97
4CC00501R9	RAD	U-235	0.0372	0.01	pCi/g		MSOIL	POND 4	0-0.5	5/14/97
4CC00801R9	RAD	U-235	0.0677	0.01	pCi/g		MSOIL	POND 7	0-0.5	5/14/97
4CC00901R9	RAD	U-235	0.0516	0.01	pCi/g		MSOIL	POND 8	0-0.5	5/14/97
4CC01001R9	RAD	U-235	0.0702	0.02	pCi/g		MSOIL	POND 9	0-0.5	5/14/97
4CC01301R9	RAD	U-235	0.082	0.02	pCi/g		MSOIL	POND 11	0-0.5	5/14/97
4CC01701R9	RAD	U-235	0.0379	0.01	pCi/g		MSOIL	POND 15	0-0.5	5/14/97
4CC01901R9	RAD	U-235	0.0663	0.01	pCi/g		MSOIL	POND 16	0-0.5	5/14/97
4CC02201R9	RAD	U-235	0.0502	0.01	pCi/g		MSOIL	POND 19	0-0.5	5/14/97
4CC02501R9	RAD	U-235	0.0795	0.02	pCi/g		MSOIL	POND 22	0-0.5	5/14/97
4CC02601R9	RAD	U-235	0.0447	0.01	pCi/g		MSOIL	POND 23	0-0.5	5/14/97
4CC02602R9	RAD	U-235	0.0402	0.01	pCi/g		MSOIL	POND 23	0-0.5	5/14/97
4CC02701R9	RAD	U-235	0.0711	0.02	pCi/g		MSOIL	POND 24	0-0.5	5/14/97
4CC02901R9	RAD	U-235	0.0565	0.01	pCi/g		MSOIL	POND 26	0-0.5	5/14/97
4CC03101R9	RAD	U-235	0.0334	0.01	pCi/g		MSOIL	POND 28	0-0.5	5/14/97
4CC03301R9	RAD	U-235	0.0453	0.01	pCi/g		MSOIL	POND 30	0-0.5	5/14/97
40400201R4	RAD	U-235	1.6	0.30	pCi/g		SUR	INLET 2	0.17-0.67	7/18/95
40400201U9	RAD	U-235	0.93	0.10	pCi/g		SOIL	INLET 2	0.17-0.67	7/18/95
40400202R4	RAD	U-235	1.6	0.20	pCi/g		SUR	INLET 2	0.17-0.67	7/18/95

Sample no.	Analysis	Compound	Conc	Rad uncrt	Units	Q flags	Matrix	Type location	Depth (ft)	Sample date
40400202U9	RAD	U-235	1.07	0.11	pCi/g		SOIL	INLET 2	0.17-0.67	7/18/95
HG521301F7	RAD	U-235	0.432	0.15	pCi/g	J	SOIL	SA 31	0-1	10/9/97
HG522201F7	RAD	U-235	0.378	0.14	pCi/g	J	SOIL	SA 40	0-1	10/9/97
HG521401F7	RAD	U-235	0.373	0.13	pCi/g	J	SOIL	SA 32	0-1	10/9/97
HG520601F7	RAD	U-235	0.269	0.15	pCi/g	U	SOIL	SA 24	0-1	10/8/97
HG520501F7	RAD	U-235	0.221	0.09	pCi/g	J	SOIL	SA 23	0-1	10/8/97
HG520101F7	RAD	U-235	0.213	0.08	pCi/g	J	SOIL	SA 19	0-1	10/8/97
HG520801F7	RAD	U-235	0.21	0.14	pCi/g	U	SOIL	SA 26	0-1	10/8/97
HG520401F7	RAD	U-235	0.166	0.08	pCi/g	UJ	SOIL	SA 22	0-1	10/8/97
HG520201F7	RAD	U-235	0.155	0.08	pCi/g	UJ	SOIL	SA 20	0-1	10/8/97
HG521201F7	RAD	U-235	0.134	0.08	pCi/g	U	SOIL	SA 30	0-1	10/9/97
HG522401F7	RAD	U-235	0.129	0.11	pCi/g	U	SOIL	SA 42	0-1	10/9/97
HG521601F7	RAD	U-235	0.125	0.10	pCi/g	U	SOIL	SA 34	0-1	10/9/97
HG521001F7	RAD	U-235	0.122	0.09	pCi/g	U	SOIL	SA 28	0-1	10/8/97
HG520901F7	RAD	U-235	0.114	0.13	pCi/g	U	SOIL	SA 27	0-1	10/8/97
HG522501F7	RAD	U-235	0.102	0.09	pCi/g	U	SOIL	SA 43	0-1	10/9/97
HG520001F7	RAD	U-235	0.0975	0.08	pCi/g	U	SOIL	SA 18	0-1	10/8/97
HG522701F7	RAD	U-235	0.0943	0.10	pCi/g	U	SOIL	SA 45	0-1	10/9/97
HG521901F7	RAD	U-235	0.0925	0.07	pCi/g	U	SOIL	SA 37	0-1	10/9/97
HG520701F7	RAD	U-235	0.0791	0.09	pCi/g	U	SOIL	SA 25	0-1	10/8/97
HG522101F7	RAD	U-235	0.0733	0.11	pCi/g	U	SOIL	SA 39	0-1	10/9/97
HG520401R9	RAD	U-235	0.0706	0.02	pCi/g	J	SOIL	SA 22	0-1	10/8/97
HG521301R9	RAD	U-235	0.07	0.02	pCi/g	J	SOIL	SA 31	0-1	10/9/97
HG521801F7	RAD	U-235	0.0638	0.10	pCi/g	U	SOIL	SA 36	0-1	10/9/97
HG521001R9	RAD	U-235	0.0613	0.02	pCi/g	J	SOIL	SA 28	0-1	10/8/97
HG522301R9	RAD	U-235	0.0594	0.02	pCi/g	J	SOIL	SA 41	0-1	10/9/97
HG520801R9	RAD	U-235	0.0573	0.02	pCi/g	J	SOIL	SA 26	0-1	10/8/97
HG521901R9	RAD	U-235	0.0543	0.02	pCi/g	J	SOIL	SA 37	0-1	10/9/97
HG521201R9	RAD	U-235	0.0538	0.02	pCi/g	J	SOIL	SA 30	0-1	10/9/97
HG521401R9	RAD	U-235	0.0534	0.02	pCi/g	J	SOIL	SA 32	0-1	10/9/97
HG520601R9	RAD	U-235	0.0517	0.02	pCi/g	J	SOIL	SA 24	0-1	10/8/97
HG520101R9	RAD	U-235	0.0512	0.02	pCi/g	J	SOIL	SA 19	0-1	10/8/97
HG520701R9	RAD	U-235	0.0491	0.02	pCi/g	J	SOIL	SA 25	0-1	10/8/97
HG520501R9	RAD	U-235	0.048	0.02	pCi/g	J	SOIL	SA 23	0-1	10/8/97
HG522901R9	RAD	U-235	0.0472	0.02	pCi/g	J	SOIL	SA 47	0-1	10/9/97
HG520301F7	RAD	U-235	0.0467	0.08	pCi/g	U	SOIL	SA 21	0-1	10/8/97
HG520001R9	RAD	U-235	0.0465	0.02	pCi/g	J	SOIL	SA 18	0-1	10/8/97
HG521801R9	RAD	U-235	0.0454	0.02	pCi/g	J	SOIL	SA 36	0-1	10/9/97
HG520201R9	RAD	U-235	0.0448	0.02	pCi/g	J	SOIL	SA 20	0-1	10/8/97
HG522001R9	RAD	U-235	0.0446	0.02	pCi/g	J	SOIL	SA 38	0-1	10/9/97
HG520102R9	RAD	U-235	0.0443	0.02	pCi/g	J	SOIL	SA 19	0-1	10/8/97
HG522102R9	RAD	U-235	0.0437	0.02	pCi/g	J	SOIL	SA 39	0-1	10/9/97
HG522801R9	RAD	U-235	0.0413	0.02	pCi/g	J	SOIL	SA 46	0-1	10/9/97
HG521701R9	RAD	U-235	0.0413	0.02	pCi/g	J	SOIL	SA 36	0-1	10/9/97
HG522401R9	RAD	U-235	0.0412	0.02	pCi/g	J	SOIL	SA 42	0-1	10/9/97
HG521101R9	RAD	U-235	0.0391	0.02	pCi/g	J	SOIL	SA 29	0-1	10/8/97
HG522101R9	RAD	U-235	0.0385	0.01	pCi/g	J	SOIL	SA 39	0-1	10/9/97
HG521601R9	RAD	U-235	0.0369	0.01	pCi/g	J	SOIL	SA 34	0-1	10/9/97
HG520301R9	RAD	U-235	0.0367	0.02	pCi/g	J	SOIL	SA 21	0-1	10/8/97
HG521501R9	RAD	U-235	0.0327	0.01	pCi/g	J	SOIL	SA 33	0-1	10/9/97
HG520901R9	RAD	U-235	0.0299	0.01	pCi/g	J	SOIL	SA 27	0-1	10/8/97
HG521101F7	RAD	U-235	0.0294	0.10	pCi/g	U	SOIL	SA 29	0-1	10/8/97
HG520102F7	RAD	U-235	0.0281	0.08	pCi/g	U	SOIL	SA 19	0-1	10/8/97
HG522901F7	RAD	U-235	0.028	0.11	pCi/g	U	SOIL	SA 47	0-1	10/9/97
HG522201R9	RAD	U-235	0.0279	0.01	pCi/g	U	SOIL	SA 40	0-1	10/9/97
HG522601R9	RAD	U-235	0.0259	0.01	pCi/g	U	SOIL	SA 44	0-1	10/9/97
HG522701R9	RAD	U-235	0.0221	0.01	pCi/g	J	SOIL	SA 45	0-1	10/9/97
HG522501R9	RAD	U-235	0.0165	0.01	pCi/g	U	SOIL	SA 43	0-1	10/9/97
HG522801F7	RAD	U-235	0.00668	0.10	pCi/g	U	SOIL	SA 46	0-1	10/9/97
HG521701F7	RAD	U-235	0	0.06	pCi/g	U	SOIL	SA 36	0-1	10/9/97
HG522001F7	RAD	U-235	-0.00411	0.09	pCi/g	U	SOIL	SA 38	0-1	10/9/97

Sample no.	Analysis	Compound	Conc	Rad uncrt	Units	Q flags	Matrix	Type location	Depth (ft)	Sample date
HG521501F7	RAD	U-235	-0.00422	0.17	pCi/g	U	SOIL	SA 33	0-1	10/9/97
HG522601F7	RAD	U-235	-0.00739	0.10	pCi/g	U	SOIL	SA 44	0-1	10/9/97
HG522102F7	RAD	U-235	-0.125	0.16	pCi/g	U	SOIL	SA 39	0-1	10/9/97
40400401U9	RAD	U-235	0.103	0.02	pCi/g		SOIL	INLET 2	1.5	7/18/95
40400601R4	RAD	U-235	0.31	0.05	pCi/g		SUR	INLET 3	1.5	7/18/95
40400601U9	RAD	U-235	0.15	0.02	pCi/g		SOIL	INLET 3	1.5	7/18/95
40400801U9	RAD	U-235	0.11	0.03	pCi/g		SOIL	INLET 4	1.5	7/18/95
4CC01801R4	RAD	U-235	0.103	0.07	pCi/g	U	SOIL	POND 15	2-4	5/15/97
4CC01801R9	RAD	U-235	0.075	0.02	pCi/g		MSOIL	POND 15	2-4	5/14/97
4CP06101R4	RAD	U-235	-0.0192	0.06	pCi/g	U	SOIL	PIPE 2	2-4	5/15/97
4CP06101R9	RAD	U-235	0.0733	0.02	pCi/g		MSOIL	PIPE 2	2-4	5/14/97
4CC01101R4	RAD	U-235	-0.0473	0.07	pCi/g	U	SOIL	POND 9	3-5	5/15/97
4CC01101R9	RAD	U-235	0.0549	0.01	pCi/g		MSOIL	POND 9	3-5	5/14/97
4CN03801R4	RAD	U-235	0.224	0.10	pCi/g	UJ	SOIL	TRENCH 1 #4	3.5	6/2/97
4CN03801R9	RAD	U-235	0.0276	0.01	pCi/g		MSOIL	TRENCH 1 #4	3.5	6/2/97
4CN04301R4	RAD	U-235	0.321	0.10	pCi/g	U	SOIL	TRENCH 2 #1	3.5	6/2/97
4CN04301R9	RAD	U-235	0.0601	0.01	pCi/g		MSOIL	TRENCH 2 #1	3.5	6/2/97
4CC00301R4	RAD	U-235	0.0619	0.07	pCi/g	U	SOIL	POND 2	3.5-5.5	5/15/97
4CC00301R9	RAD	U-235	0.139	0.02	pCi/g		MSOIL	POND 2	3.5-5.5	5/14/97
4CN03501R4	RAD	U-235	-0.0373	0.14	pCi/g	U	SOIL	TRENCH 1 #1	4	6/2/97
4CN03501R9	RAD	U-235	0.0483	0.01	pCi/g		MSOIL	TRENCH 1 #1	4	6/2/97
4CN03701R4	RAD	U-235	0.183	0.12	pCi/g	U	SOIL	TRENCH 1 #3	4	6/2/97
4CN03701R9	RAD	U-235	0.0472	0.01	pCi/g		MSOIL	TRENCH 1 #3	4	6/2/97
4CN03601R4	RAD	U-235	0.133	0.11	pCi/g	U	SOIL	TRENCH 1 #2	4.5	6/2/97
4CN03601R9	RAD	U-235	0.0531	0.01	pCi/g		MSOIL	TRENCH 1 #2	4.5	6/2/97
4CN03602R4	RAD	U-235	0.103	0.11	pCi/g	U	SOIL	TRENCH 1 #2	4.5	6/2/97
4CN03602R9	RAD	U-235	0.0705	0.01	pCi/g		MSOIL	TRENCH 1 #2	4.5	6/2/97
4CP05901R9	RAD	U-235	0.0777	0.01	pCi/g		MSOIL	PIPE 1	5-7	5/14/97
4CP06001R9	RAD	U-235	0.133	0.02	pCi/g		MSOIL	PIPE 2	5-7	5/14/97
4CP06201R9	RAD	U-235	0.119	0.02	pCi/g		MSOIL	PIPE 3	5-7	5/14/97
4CP06301R9	RAD	U-235	0.0522	0.01	pCi/g		MSOIL	PIPE 4	5-7	5/14/97
4CN05101R4	RAD	U-235	0.0984	0.12	pCi/g	U	SOIL	TRENCH 3 #1	5.6	6/2/97
4CN05101R9	RAD	U-235	0.0573	0.01	pCi/g		MSOIL	TRENCH 3 #1	5.6	6/2/97
4CN05201R4	RAD	U-235	0.177	0.09	pCi/g	U	SOIL	TRENCH 3 #2	6	6/2/97
4CN05201R9	RAD	U-235	0.0457	0.01	pCi/g		MSOIL	TRENCH 3 #2	6	6/2/97
4CN05401R4	RAD	U-235	0.162	0.14	pCi/g	U	SOIL	TRENCH 3 #4	6.5	6/2/97
4CN05401R9	RAD	U-235	0.0584	0.01	pCi/g		MSOIL	TRENCH 3 #4	6.5	6/2/97
4CN05301R4	RAD	U-235	0.128	0.10	pCi/g	U	SOIL	TRENCH 3 #3	6.8	6/2/97
4CN05301R9	RAD	U-235	0.0772	0.01	pCi/g		MSOIL	TRENCH 3 #3	6.8	6/2/97
4CN04601R4	RAD	U-235	0.113	0.09	pCi/g	U	SOIL	TRENCH 2 #4	7	6/2/97
4CN04601R9	RAD	U-235	0.0334	0.01	pCi/g		MSOIL	TRENCH 2 #4	7	6/2/97
4CN04501R4	RAD	U-235	0.0503	0.09	pCi/g	U	SOIL	TRENCH 2 #3	7.5	6/2/97
4CN04501R9	RAD	U-235	0.0225	0.01	pCi/g		MSOIL	TRENCH 2 #3	7.5	6/2/97
4CN04401R4	RAD	U-235	0.0149	0.11	pCi/g	U	SOIL	TRENCH 2 #2	8	6/2/97
4CN04401R9	RAD	U-235	0.0941	0.02	pCi/g		MSOIL	TRENCH 2 #2	8	6/2/97
40400101U9	RAD	U-238	10.7	0.80	pCi/g		SOIL	INLET 1	0-0.5	7/18/95
40400301U9	RAD	U-238	1.89	0.13	pCi/g		SOIL	INLET 2	0-0.5	7/18/95
40400501U9	RAD	U-238	7.8	0.50	pCi/g		SOIL	INLET 3	0-0.5	7/18/95
40400701U9	RAD	U-238	17.1	1.50	pCi/g		SOIL	INLET 4	0-0.5	7/18/95
4CC00201R9	RAD	U-238	0.876	0.07	pCi/g		MSOIL	POND 2	0-0.5	5/14/97
4CC00501R9	RAD	U-238	0.932	0.08	pCi/g		MSOIL	POND 4	0-0.5	5/14/97
4CC00801R9	RAD	U-238	0.805	0.07	pCi/g		MSOIL	POND 7	0-0.5	5/14/97
4CC00901R9	RAD	U-238	1	0.08	pCi/g		MSOIL	POND 8	0-0.5	5/14/97
4CC01001R9	RAD	U-238	1	0.08	pCi/g		MSOIL	POND 9	0-0.5	5/14/97
4CC01301R9	RAD	U-238	1.1	0.08	pCi/g		MSOIL	POND 11	0-0.5	5/14/97
4CC01701R9	RAD	U-238	0.938	0.08	pCi/g		MSOIL	POND 15	0-0.5	5/14/97
4CC01901R9	RAD	U-238	1.04	0.08	pCi/g		MSOIL	POND 16	0-0.5	5/14/97
4CC02201R9	RAD	U-238	0.871	0.07	pCi/g		MSOIL	POND 19	0-0.5	5/14/97
4CC02501R9	RAD	U-238	1.03	0.08	pCi/g		MSOIL	POND 22	0-0.5	5/14/97
4CC02601R9	RAD	U-238	0.848	0.07	pCi/g		MSOIL	POND 23	0-0.5	5/14/97
4CC02602R9	RAD	U-238	0.841	0.07	pCi/g		MSOIL	POND 23	0-0.5	5/14/97

Sample no.	Analysis	Compound	Conc	Rad uncrt	Units	Q flags	Matrix	Type location	Depth (ft)	Sample date
4CC02701R9	RAD	U-238	1.56	0.11	pCi/g		MSOIL	POND 24	0-0.5	5/14/97
4CC02901R9	RAD	U-238	0.918	0.08	pCi/g		MSOIL	POND 26	0-0.5	5/14/97
4CC03101R9	RAD	U-238	1.01	0.08	pCi/g		MSOIL	POND 28	0-0.5	5/14/97
4CC03301R9	RAD	U-238	0.879	0.07	pCi/g		MSOIL	POND 30	0-0.5	5/14/97
40400201U9	RAD	U-238	28.8	1.80	pCi/g		SOIL	INLET 2	0.17-0.67	7/18/95
40400202U9	RAD	U-238	35	2.00	pCi/g		SOIL	INLET 2	0.17-0.67	7/18/95
HG520501R9	RAD	U-238	1.23	0.32	pCi/g		SOIL	SA 23	0-1	10/8/97
HG520901R9	RAD	U-238	0.975	0.26	pCi/g		SOIL	SA 27	0-1	10/8/97
HG520701R9	RAD	U-238	0.957	0.26	pCi/g		SOIL	SA 25	0-1	10/8/97
HG520401R9	RAD	U-238	0.946	0.25	pCi/g		SOIL	SA 22	0-1	10/8/97
HG520601R9	RAD	U-238	0.917	0.24	pCi/g		SOIL	SA 24	0-1	10/8/97
HG522101R9	RAD	U-238	0.913	0.24	pCi/g		SOIL	SA 39	0-1	10/9/97
HG521001R9	RAD	U-238	0.908	0.24	pCi/g		SOIL	SA 28	0-1	10/8/97
HG522001R9	RAD	U-238	0.889	0.24	pCi/g		SOIL	SA 38	0-1	10/9/97
HG521601R9	RAD	U-238	0.885	0.24	pCi/g		SOIL	SA 34	0-1	10/9/97
HG520301R9	RAD	U-238	0.878	0.23	pCi/g		SOIL	SA 21	0-1	10/8/97
HG520201R9	RAD	U-238	0.874	0.23	pCi/g		SOIL	SA 20	0-1	10/8/97
HG521101R9	RAD	U-238	0.871	0.23	pCi/g		SOIL	SA 29	0-1	10/8/97
HG522301R9	RAD	U-238	0.868	0.23	pCi/g		SOIL	SA 41	0-1	10/9/97
HG521201R9	RAD	U-238	0.863	0.23	pCi/g		SOIL	SA 30	0-1	10/9/97
HG521501R9	RAD	U-238	0.862	0.23	pCi/g		SOIL	SA 33	0-1	10/9/97
HG521301R9	RAD	U-238	0.861	0.23	pCi/g		SOIL	SA 31	0-1	10/9/97
HG522801R9	RAD	U-238	0.856	0.23	pCi/g		SOIL	SA 46	0-1	10/9/97
HG522501R9	RAD	U-238	0.853	0.23	pCi/g		SOIL	SA 43	0-1	10/9/97
HG522901R9	RAD	U-238	0.842	0.23	pCi/g		SOIL	SA 47	0-1	10/9/97
HG520801R9	RAD	U-238	0.841	0.23	pCi/g		SOIL	SA 26	0-1	10/8/97
HG520101R9	RAD	U-238	0.837	0.22	pCi/g		SOIL	SA 19	0-1	10/8/97
HG520001R9	RAD	U-238	0.832	0.22	pCi/g		SOIL	SA 18	0-1	10/8/97
HG522102R9	RAD	U-238	0.821	0.22	pCi/g		SOIL	SA 39	0-1	10/9/97
HG522201R9	RAD	U-238	0.819	0.22	pCi/g		SOIL	SA 40	0-1	10/9/97
HG521801R9	RAD	U-238	0.799	0.21	pCi/g		SOIL	SA 36	0-1	10/9/97
HG521401R9	RAD	U-238	0.797	0.21	pCi/g		SOIL	SA 32	0-1	10/9/97
HG521701R9	RAD	U-238	0.776	0.21	pCi/g		SOIL	SA 36	0-1	10/9/97
HG522401R9	RAD	U-238	0.774	0.21	pCi/g		SOIL	SA 42	0-1	10/9/97
HG520102R9	RAD	U-238	0.737	0.20	pCi/g		SOIL	SA 19	0-1	10/8/97
HG522601R9	RAD	U-238	0.726	0.20	pCi/g		SOIL	SA 44	0-1	10/9/97
HG522701R9	RAD	U-238	0.724	0.20	pCi/g		SOIL	SA 45	0-1	10/9/97
HG521901R9	RAD	U-238	0.707	0.19	pCi/g		SOIL	SA 37	0-1	10/9/97
40400401U9	RAD	U-238	2.36	0.18	pCi/g		SOIL	INLET 2	1.5	7/18/95
40400601U9	RAD	U-238	4.6	0.30	pCi/g		SOIL	INLET 3	1.5	7/18/95
40400801U9	RAD	U-238	2.2	0.30	pCi/g		SOIL	INLET 4	1.5	7/18/95
4CC01801R9	RAD	U-238	1.03	0.08	pCi/g		MSOIL	POND 15	2-4	5/14/97
4CP06101R9	RAD	U-238	1.17	0.09	pCi/g		MSOIL	PIPE 2	2-4	5/14/97
4CC01101R9	RAD	U-238	1.13	0.09	pCi/g		MSOIL	POND 9	3-5	5/14/97
4CN03801R9	RAD	U-238	0.73	0.06	pCi/g		MSOIL	TRENCH 1 #4	3.5	6/2/97
4CN04301R9	RAD	U-238	1.7	0.12	pCi/g		MSOIL	TRENCH 2 #1	3.5	6/2/97
4CC00301R9	RAD	U-238	2.14	0.15	pCi/g		MSOIL	POND 2	3.5-5.5	5/14/97
4CN03501R9	RAD	U-238	1.27	0.09	pCi/g		MSOIL	TRENCH 1 #1	4	6/2/97
4CN03701R9	RAD	U-238	0.785	0.06	pCi/g		MSOIL	TRENCH 1 #3	4	6/2/97
4CN03601R9	RAD	U-238	1.14	0.08	pCi/g		MSOIL	TRENCH 1 #2	4.5	6/2/97
4CN03602R9	RAD	U-238	1.19	0.09	pCi/g		MSOIL	TRENCH 1 #2	4.5	6/2/97
4CP05901R9	RAD	U-238	2.07	0.14	pCi/g		MSOIL	PIPE 1	5-7	5/14/97
4CP06001R9	RAD	U-238	2.44	0.17	pCi/g		MSOIL	PIPE 2	5-7	5/14/97
4CP06201R9	RAD	U-238	2.98	0.20	pCi/g		MSOIL	PIPE 3	5-7	5/14/97
4CP06301R9	RAD	U-238	1.44	0.11	pCi/g		MSOIL	PIPE 4	5-7	5/14/97
4CN05101R9	RAD	U-238	0.776	0.06	pCi/g		MSOIL	TRENCH 3 #1	5.6	6/2/97
4CN05201R9	RAD	U-238	0.732	0.06	pCi/g		MSOIL	TRENCH 3 #2	6	6/2/97
4CN05401R9	RAD	U-238	1.61	0.11	pCi/g		MSOIL	TRENCH 3 #4	6.5	6/2/97
4CN05301R9	RAD	U-238	1.44	0.10	pCi/g		MSOIL	TRENCH 3 #3	6.8	6/2/97
4CN04601R9	RAD	U-238	0.776	0.06	pCi/g		MSOIL	TRENCH 2 #4	7	6/2/97
4CN04501R9	RAD	U-238	0.866	0.07	pCi/g		MSOIL	TRENCH 2 #3	7.5	6/2/97

Sample no.	Analysis	Compound	Conc	Rad uncrt	Units	Q flags	Matrix	Type location	Depth (ft)	Sample date
4CN04401R9	RAD	U-238	1.3	0.09	pCi/g		MSOIL	TRENCH 2 #2	8	6/2/97
40400101OS	SEMIS - CLP	Unknown	160		ug/kg	JN	SOIL	INLET 1	0-0.5	7/18/95
40400101OS	SEMIS - CLP	Unknown	170		ug/kg	R	SOIL	INLET 1	0-0.5	7/18/95
40400101OS	SEMIS - CLP	Unknown	490		ug/kg	JN	SOIL	INLET 1	0-0.5	7/18/95
40400101OS	SEMIS - CLP	Unknown	700		ug/kg	JN	SOIL	INLET 1	0-0.5	7/18/95
40400301OS	SEMIS - CLP	Unknown	210		ug/kg	R	SOIL	INLET 2	0-0.5	7/18/95
40400501OS	SEMIS - CLP	Unknown	150		ug/kg	JN	SOIL	INLET 3	0-0.5	7/18/95
40400501OS	SEMIS - CLP	Unknown	180		ug/kg	R	SOIL	INLET 3	0-0.5	7/18/95
40400701OS	SEMIS - CLP	Unknown	160		ug/kg	JN	SOIL	INLET 4	0-0.5	7/18/95
40400701OS	SEMIS - CLP	Unknown	170		ug/kg	JN	SOIL	INLET 4	0-0.5	7/18/95
40400701OS	SEMIS - CLP	Unknown	800		ug/kg	JN	SOIL	INLET 4	0-0.5	7/18/95
40400701OS	SEMIS - CLP	Unknown	880		ug/kg	JN	SOIL	INLET 4	0-0.5	7/18/95
40400701OS	SEMIS - CLP	Unknown	1600		ug/kg	JN	SOIL	INLET 4	0-0.5	7/18/95
40400201OS	SEMIS - CLP	Unknown	200		ug/kg	R	SOIL	INLET 2	0.17-0.67	7/18/95
40400201OS	SEMIS - CLP	Unknown	320		ug/kg	JN	SOIL	INLET 2	0.17-0.67	7/18/95
40400201OS	SEMIS - CLP	Unknown	340		ug/kg	JN	SOIL	INLET 2	0.17-0.67	7/18/95
40400201OS	SEMIS - CLP	Unknown	1500		ug/kg	JN	SOIL	INLET 2	0.17-0.67	7/18/95
40400202OS	SEMIS - CLP	Unknown	200		ug/kg	R	SOIL	INLET 2	0.17-0.67	7/18/95
40400202OS	SEMIS - CLP	Unknown	490		ug/kg	JN	SOIL	INLET 2	0.17-0.67	7/18/95
40400202OS	SEMIS - CLP	Unknown	610		ug/kg	JN	SOIL	INLET 2	0.17-0.67	7/18/95
40400401OS	SEMIS - CLP	Unknown	170		ug/kg	JN	SOIL	INLET 2	0.17-0.67	7/18/95
40400401OS	SEMIS - CLP	Unknown	190		ug/kg	JN	SOIL	INLET 2	0.17-0.67	7/18/95
40400401OS	SEMIS - CLP	Unknown	210		ug/kg	R	SOIL	INLET 2	0.17-0.67	7/18/95
40400401OS	SEMIS - CLP	Unknown	230		ug/kg	JN	SOIL	INLET 2	0.17-0.67	7/18/95
40400401OS	SEMIS - CLP	Unknown	320		ug/kg	JN	SOIL	INLET 2	0.17-0.67	7/18/95
40400401OS	SEMIS - CLP	Unknown	660		ug/kg	JN	SOIL	INLET 2	0.17-0.67	7/18/95
40400601OS	SEMIS - CLP	Unknown	200		ug/kg	JN	SOIL	INLET 3	1.5	7/18/95
40400601OS	SEMIS - CLP	Unknown	230		ug/kg	JN	SOIL	INLET 3	1.5	7/18/95
40400801OS	SEMIS - CLP	Unknown	190		ug/kg	JN	SOIL	INLET 4	1.5	7/18/95
4CC01801SV	SEMIS - CLP	Unknown	80		ug/kg	JBU	SOLID	POND 15	2-4	5/15/97
4CC01801SV	SEMIS - CLP	Unknown	100		ug/kg	JBU	SOLID	POND 15	2-4	5/15/97
4CC01801SV	SEMIS - CLP	Unknown	200		ug/kg	JBU	SOLID	POND 15	2-4	5/15/97
4CC01801SV	SEMIS - CLP	Unknown	400		ug/kg	JBU	SOLID	POND 15	2-4	5/15/97
4CP06101SV	SEMIS - CLP	Unknown	100		ug/kg	JN	SOLID	PIPE 2	2-4	5/15/97
4CP06101SV	SEMIS - CLP	Unknown	200		ug/kg	JN	SOLID	PIPE 2	2-4	5/15/97
4CP06101SV	SEMIS - CLP	Unknown	400		ug/kg	JN	SOLID	PIPE 2	2-4	5/15/97
4CP06101SV	SEMIS - CLP	Unknown	500		ug/kg	JBU	SOLID	PIPE 2	2-4	5/15/97
4CP06101SV	SEMIS - CLP	Unknown	600		ug/kg	JBU	SOLID	PIPE 2	2-4	5/15/97
4CP06101SV	SEMIS - CLP	Unknown	1000		ug/kg	JBU	SOLID	PIPE 2	2-4	5/15/97
4CC01101SV	SEMIS - CLP	Unknown	100		ug/kg	JN	SOLID	POND 9	3-5	5/15/97
4CC01101SV	SEMIS - CLP	Unknown	300		ug/kg	JBU	SOLID	POND 9	3-5	5/15/97
4CC01101SV	SEMIS - CLP	Unknown	500		ug/kg	JBU	SOLID	POND 9	3-5	5/15/97
4CC00301SV	SEMIS - CLP	Unknown	100		ug/kg	JBU	SOLID	POND 2	3.5-5.5	5/15/97
4CC00301SV	SEMIS - CLP	Unknown	200		ug/kg	JBU	SOLID	POND 2	3.5-5.5	5/15/97
4CC00301SV	SEMIS - CLP	Unknown	500		ug/kg	JBU	SOLID	POND 2	3.5-5.5	5/15/97
4CC00302SV	SEMIS - CLP	Unknown	100		ug/kg	JN	SOLID	POND 2	3.5-5.5	5/15/97
4CC00302SV	SEMIS - CLP	Unknown	200		ug/kg	JBU	SOLID	POND 2	3.5-5.5	5/15/97
4CC00302SV	SEMIS - CLP	Unknown	400		ug/kg	JBU	SOLID	POND 2	3.5-5.5	5/15/97
4CC00302SV	SEMIS - CLP	Unknown	500		ug/kg	JBU	SOLID	POND 2	3.5-5.5	5/15/97
40400101OS	SEMIS - CLP	Unknown Alkane	190		ug/kg	JN	SOIL	INLET 1	0-0.5	7/18/95
40400101OS	SEMIS - CLP	Unknown Alkane	220		ug/kg	JN	SOIL	INLET 1	0-0.5	7/18/95
40400301OS	SEMIS - CLP	Unknown Alkane	190		ug/kg	JN	SOIL	INLET 2	0-0.5	7/18/95
40400701OS	SEMIS - CLP	Unknown Alkane	200		ug/kg	JN	SOIL	INLET 4	0-0.5	7/18/95
40400201OS	SEMIS - CLP	Unknown Alkane	200		ug/kg	JN	SOIL	INLET 2	0.17-0.67	7/18/95
40400202OS	SEMIS - CLP	Unknown Alkane	200		ug/kg	JN	SOIL	INLET 2	0.17-0.67	7/18/95
40400202OS	SEMIS - CLP	Unknown Alkane	220		ug/kg	JN	SOIL	INLET 2	0.17-0.67	7/18/95
40400101OS	SEMIS - CLP	Unknown PCB	160		ug/kg	JN	SOIL	INLET 1	0-0.5	7/18/95
40400201OS	SEMIS - CLP	Unknown PCB	140		ug/kg	JN	SOIL	INLET 2	0.17-0.67	7/18/95
40400201OS	SEMIS - CLP	Unknown PCB	160		ug/kg	JN	SOIL	INLET 2	0.17-0.67	7/18/95
40400201OS	SEMIS - CLP	Unknown PCB	220		ug/kg	JN	SOIL	INLET 2	0.17-0.67	7/18/95
40400201OS	SEMIS - CLP	Unknown PCB	230		ug/kg	JN	SOIL	INLET 2	0.17-0.67	7/18/95

Sample no.	Analysis	Compound	Conc	Rad uncrt	Units	Q flags	Matrix	Type location	Depth (ft)	Sample date
40400101C1	INORG	Vanadium	40.1		mg/kg		SOIL	INLET 1	0-0.5	7/18/95
40400301C1	INORG	Vanadium	33.3		mg/kg		SOIL	INLET 2	0-0.5	7/18/95
40400501C1	INORG	Vanadium	39.5		mg/kg		SOIL	INLET 3	0-0.5	7/18/95
40400701C1	INORG	Vanadium	42.7		mg/kg		SOIL	INLET 4	0-0.5	7/18/95
4CC03501LM	INORG	Vanadium	35.9		mg/kg		SOIL	POND 32	0-0.5	7/16/97
4CC03601LM	INORG	Vanadium	39.7		mg/kg		SOIL	POND 33	0-0.5	7/16/97
4CC03701LM	INORG	Vanadium	10.7		mg/kg	B	SOIL	POND 34	0-0.5	7/16/97
4CC03801LM	INORG	Vanadium	38.2		mg/kg		SOIL	POND 35	0-0.5	7/16/97
4CC03901LM	INORG	Vanadium	32.6		mg/kg		SOIL	POND 36	0-0.5	7/16/97
4CC04001LM	INORG	Vanadium	32.6		mg/kg		SOIL	POND 37	0-0.5	7/16/97
4CC04002LM	INORG	Vanadium	30.4		mg/kg		SOIL	POND 37	0-0.5	7/16/97
40400201C1	INORG	Vanadium	35		mg/kg		SOIL	INLET 2	0.17-0.67	7/18/95
40400202C1	INORG	Vanadium	43.6		mg/kg		SOIL	INLET 2	0.17-0.67	7/18/95
40400401C1	INORG	Vanadium	38.1		mg/kg		SOIL	INLET 2	0.17-0.67	7/18/95
HG520301C1	INORG	Vanadium	37.5		mg/kg	P	SOIL	SA 21	0-1	10/8/97
HG523801N2	INORG	Vanadium	37		mg/kg	P	SOIL	SA 56	0-1	10/13/97
HG520101C1	INORG	Vanadium	36.6		mg/kg	P	SOIL	SA 19	0-1	10/8/97
HG523001C1	INORG	Vanadium	36.2		mg/kg	P	SOIL	SA 48	0-1	10/9/97
HG520102C1	INORG	Vanadium	35.5		mg/kg	P	SOIL	SA 19	0-1	10/8/97
HG522601C1	INORG	Vanadium	33.7		mg/kg	P	SOIL	SA 44	0-1	10/9/97
HG524102C1	INORG	Vanadium	33.7		mg/kg	P	SOIL	SA 59	0-1	10/13/97
HG521401C1	INORG	Vanadium	33.1		mg/kg	P	SOIL	SA 32	0-1	10/9/97
HG523601C1	INORG	Vanadium	32.7		mg/kg	P	SOIL	SA 54	0-1	10/13/97
HG523501C1	INORG	Vanadium	32.3		mg/kg	P	SOIL	SA 53	0-1	10/13/97
HG524201C1	INORG	Vanadium	32.2		mg/kg	P	SOIL	SA 60	0-1	10/13/97
HG522101C1	INORG	Vanadium	32		mg/kg	P	SOIL	SA 39	0-1	10/9/97
HG524401C1	INORG	Vanadium	31.9		mg/kg	P	SOIL	SA 62	0-1	10/13/97
HG520501C1	INORG	Vanadium	31.6		mg/kg	P	SOIL	SA 23	0-1	10/8/97
HG522401C1	INORG	Vanadium	31.4		mg/kg	P	SOIL	SA 42	0-1	10/9/97
HG520401C1	INORG	Vanadium	31.3		mg/kg	P	SOIL	SA 22	0-1	10/8/97
HG521701C1	INORG	Vanadium	31.3		mg/kg	P	SOIL	SA 36	0-1	10/9/97
HG521101C1	INORG	Vanadium	31.2		mg/kg	P	SOIL	SA 29	0-1	10/8/97
HG523301C1	INORG	Vanadium	31.1		mg/kg	P	SOIL	SA 51	0-1	10/13/97
HG522102C1	INORG	Vanadium	31.1		mg/kg	P	SOIL	SA 39	0-1	10/9/97
HG520201C1	INORG	Vanadium	30.8		mg/kg	P	SOIL	SA 20	0-1	10/8/97
HG522501C1	INORG	Vanadium	30.7		mg/kg	P	SOIL	SA 43	0-1	10/9/97
HG522701C1	INORG	Vanadium	30.4		mg/kg	P	SOIL	SA 45	0-1	10/9/97
HG520801C1	INORG	Vanadium	30.1		mg/kg	P	SOIL	SA 26	0-1	10/8/97
HG523401C1	INORG	Vanadium	30		mg/kg	P	SOIL	SA 52	0-1	10/13/97
HG520701C1	INORG	Vanadium	29.9		mg/kg	P	SOIL	SA 25	0-1	10/8/97
HG522301C1	INORG	Vanadium	29.7		mg/kg	P	SOIL	SA 41	0-1	10/9/97
HG521001C1	INORG	Vanadium	29.7		mg/kg	P	SOIL	SA 28	0-1	10/8/97
HG522901C1	INORG	Vanadium	29.6		mg/kg	P	SOIL	SA 47	0-1	10/9/97
HG522201C1	INORG	Vanadium	29.6		mg/kg	P	SOIL	SA 40	0-1	10/9/97
HG522801C1	INORG	Vanadium	29.5		mg/kg	P	SOIL	SA 46	0-1	10/9/97
HG521301C1	INORG	Vanadium	29.3		mg/kg	P	SOIL	SA 31	0-1	10/9/97
HG521901C1	INORG	Vanadium	29.1		mg/kg	P	SOIL	SA 37	0-1	10/9/97
HG523101C1	INORG	Vanadium	28.9		mg/kg	P	SOIL	SA 49	0-1	10/9/97
HG523701C1	INORG	Vanadium	28.9		mg/kg	P	SOIL	SA 55	0-1	10/13/97
HG521501C1	INORG	Vanadium	28.3		mg/kg	P	SOIL	SA 33	0-1	10/9/97
HG523801C1	INORG	Vanadium	28.1		mg/kg	P	SOIL	SA 56	0-1	10/13/97
HG522001C1	INORG	Vanadium	27.8		mg/kg	P	SOIL	SA 38	0-1	10/9/97
HG524301C1	INORG	Vanadium	27.7		mg/kg	P	SOIL	SA 61	0-1	10/13/97
HG520901C1	INORG	Vanadium	27.5		mg/kg	P	SOIL	SA 27	0-1	10/8/97
HG521601C1	INORG	Vanadium	27.5		mg/kg	P	SOIL	SA 34	0-1	10/9/97
HG521801C1	INORG	Vanadium	26.9		mg/kg	P	SOIL	SA 36	0-1	10/9/97
HG524101C1	INORG	Vanadium	26.5		mg/kg	P	SOIL	SA 59	0-1	10/13/97
HG520601C1	INORG	Vanadium	26.4		mg/kg	P	SOIL	SA 24	0-1	10/8/97
HG523201C1	INORG	Vanadium	26.2		mg/kg	P	SOIL	SA 50	0-1	10/13/97
HG520001C1	INORG	Vanadium	25.8		mg/kg	P	SOIL	SA 18	0-1	10/8/97
HG521201C1	INORG	Vanadium	24.9		mg/kg	P	SOIL	SA 30	0-1	10/9/97

Sample no.	Analysis	Compound	Conc	Rad uncrt	Units	Q flags	Matrix	Type location	Depth (ft)	Sample date
HG523901C1	INORG	Vanadium	24.4		mg/kg	P	SOIL	SA 57	0-1	10/13/97
HG524001C1	INORG	Vanadium	21.8		mg/kg	P	SOIL	SA 57	0-1	10/13/97
40400601C1	INORG	Vanadium	44		mg/kg		SOIL	INLET 3	1.5	7/18/95
40400801C1	INORG	Vanadium	35.9		mg/kg		SOIL	INLET 4	1.5	7/18/95
4CN03801C1	INORG	Vanadium	39.9		mg/kg		SOIL	TRENCH 1 #4	3.5	6/2/97
4CN04301C1	INORG	Vanadium	38.5		mg/kg		SOIL	TRENCH 2 #1	3.5	6/2/97
4CN03501C1	INORG	Vanadium	45.5		mg/kg		SOIL	TRENCH 1 #1	4	6/2/97
4CN03701C1	INORG	Vanadium	39.1		mg/kg		SOIL	TRENCH 1 #3	4	6/2/97
4CN03601C1	INORG	Vanadium	48.3		mg/kg		SOIL	TRENCH 1 #2	4.5	6/2/97
4CN03602C1	INORG	Vanadium	47.5		mg/kg		SOIL	TRENCH 1 #2	4.5	6/2/97
4CN05101C1	INORG	Vanadium	40.1		mg/kg		SOIL	TRENCH 3 #1	5.6	6/2/97
4CN05201C1	INORG	Vanadium	38.3		mg/kg		SOIL	TRENCH 3 #2	6	6/2/97
4CN05401C1	INORG	Vanadium	46.5		mg/kg		SOIL	TRENCH 3 #4	6.5	6/2/97
4CN05301C1	INORG	Vanadium	55.6		mg/kg		SOIL	TRENCH 3 #3	6.8	6/2/97
4CN04601C1	INORG	Vanadium	37		mg/kg		SOIL	TRENCH 2 #4	7	6/2/97
4CN04501C1	INORG	Vanadium	37.3		mg/kg		SOIL	TRENCH 2 #3	7.5	6/2/97
4CN04401C1	INORG	Vanadium	48.6		mg/kg		SOIL	TRENCH 2 #2	8	6/2/97
40400201CV	VOAS - CLP	Vinyl Acetate	10		ug/kg	U	SOIL	INLET 2	0.17-0.67	7/18/95
40400202CV	VOAS - CLP	Vinyl Acetate	12		ug/kg	U	SOIL	INLET 2	0.17-0.67	7/18/95
40400401CV	VOAS - CLP	Vinyl Acetate	11		ug/kg	U	SOIL	INLET 2	0.17-0.67	7/18/95
40400601CV	VOAS - CLP	Vinyl Acetate	12		ug/kg	U	SOIL	INLET 3	1.5	7/18/95
40400801CV	VOAS - CLP	Vinyl Acetate	12		ug/kg	U	SOIL	INLET 4	1.5	7/18/95
40400201CV	VOAS - CLP	Vinyl Chloride	10		ug/kg	U	SOIL	INLET 2	0.17-0.67	7/18/95
40400202CV	VOAS - CLP	Vinyl Chloride	12		ug/kg	U	SOIL	INLET 2	0.17-0.67	7/18/95
40400401CV	VOAS - CLP	Vinyl Chloride	11		ug/kg	U	SOIL	INLET 2	0.17-0.67	7/18/95
40400601CV	VOAS - CLP	Vinyl Chloride	12		ug/kg	U	SOIL	INLET 3	1.5	7/18/95
40400801CV	VOAS - CLP	Vinyl Chloride	12		ug/kg	U	SOIL	INLET 4	1.5	7/18/95
4CN03801VG	VOAS - CLP	Vinyl Chloride	11		ug/kg	U	SOIL	TRENCH 1 #4	3.5	6/2/97
4CN04301TV	VOAS - TCLP	Vinyl Chloride	50		ug/L	U	WATER	TRENCH 2 #1	3.5	6/2/97
4CN04301VG	VOAS - CLP	Vinyl Chloride	12		ug/kg	U	SOIL	TRENCH 2 #1	3.5	6/2/97
4CN03501VG	VOAS - CLP	Vinyl Chloride	12		ug/kg	U	SOIL	TRENCH 1 #1	4	6/2/97
4CN03701VG	VOAS - CLP	Vinyl Chloride	11		ug/kg	U	SOIL	TRENCH 1 #3	4	6/2/97
4CN03601VG	VOAS - CLP	Vinyl Chloride	12		ug/kg	U	SOIL	TRENCH 1 #2	4.5	6/2/97
4CN03602VG	VOAS - CLP	Vinyl Chloride	12		ug/kg	U	SOIL	TRENCH 1 #2	4.5	6/2/97
4CN05101TV	VOAS - TCLP	Vinyl Chloride	50		ug/L	U	WATER	TRENCH 3 #1	5.6	6/2/97
4CN05101VG	VOAS - CLP	Vinyl Chloride	11		ug/kg	U	SOIL	TRENCH 3 #1	5.6	6/2/97
4CN05201VG	VOAS - CLP	Vinyl Chloride	12		ug/kg	U	SOIL	TRENCH 3 #2	6	6/2/97
4CN05401VG	VOAS - CLP	Vinyl Chloride	12		ug/kg	U	SOIL	TRENCH 3 #4	6.5	6/2/97
4CN05301VG	VOAS - CLP	Vinyl Chloride	12		ug/kg	U	SOIL	TRENCH 3 #3	6.8	6/2/97
4CN04601VG	VOAS - CLP	Vinyl Chloride	11		ug/kg	U	SOIL	TRENCH 2 #4	7	6/2/97
4CN04501VG	VOAS - CLP	Vinyl Chloride	12		ug/kg	U	SOIL	TRENCH 2 #3	7.5	6/2/97
4CN04401VG	VOAS - CLP	Vinyl Chloride	12		ug/kg	U	SOIL	TRENCH 2 #2	8	6/2/97
40400201CV	VOAS - CLP	Xylene (total)	10		ug/kg	U	SOIL	INLET 2	0.17-0.67	7/18/95
40400202CV	VOAS - CLP	Xylene (total)	12		ug/kg	U	SOIL	INLET 2	0.17-0.67	7/18/95
40400401CV	VOAS - CLP	Xylene (total)	11		ug/kg	U	SOIL	INLET 2	0.17-0.67	7/18/95
40400601CV	VOAS - CLP	Xylene (total)	12		ug/kg	U	SOIL	INLET 3	1.5	7/18/95
40400801CV	VOAS - CLP	Xylene (total)	12		ug/kg	U	SOIL	INLET 4	1.5	7/18/95
4CN03801VG	VOAS - CLP	Xylene (total)	11		ug/kg	U	SOIL	TRENCH 1 #4	3.5	6/2/97
4CN04301VG	VOAS - CLP	Xylene (total)	12		ug/kg	U	SOIL	TRENCH 2 #1	3.5	6/2/97
4CN03501VG	VOAS - CLP	Xylene (total)	12		ug/kg	U	SOIL	TRENCH 1 #1	4	6/2/97
4CN03701VG	VOAS - CLP	Xylene (total)	11		ug/kg	U	SOIL	TRENCH 1 #3	4	6/2/97
4CN03601VG	VOAS - CLP	Xylene (total)	12		ug/kg	U	SOIL	TRENCH 1 #2	4.5	6/2/97
4CN03602VG	VOAS - CLP	Xylene (total)	12		ug/kg	U	SOIL	TRENCH 1 #2	4.5	6/2/97
4CN05101VG	VOAS - CLP	Xylene (total)	11		ug/kg	U	SOIL	TRENCH 3 #1	5.6	6/2/97
4CN05201VG	VOAS - CLP	Xylene (total)	12		ug/kg	U	SOIL	TRENCH 3 #2	6	6/2/97
4CN05401VG	VOAS - CLP	Xylene (total)	12		ug/kg	U	SOIL	TRENCH 3 #4	6.5	6/2/97
4CN05301VG	VOAS - CLP	Xylene (total)	12		ug/kg	U	SOIL	TRENCH 3 #3	6.8	6/2/97
4CN04601VG	VOAS - CLP	Xylene (total)	11		ug/kg	U	SOIL	TRENCH 2 #4	7	6/2/97
4CN04501VG	VOAS - CLP	Xylene (total)	12		ug/kg	U	SOIL	TRENCH 2 #3	7.5	6/2/97
4CN04401VG	VOAS - CLP	Xylene (total)	12		ug/kg	U	SOIL	TRENCH 2 #2	8	6/2/97
40400101C1	INORG	Zinc	103		mg/kg		SOIL	INLET 1	0-0.5	7/18/95

Sample no.	Analysis	Compound	Conc	Rad uncrt	Units	Q flags	Matrix	Type location	Depth (ft)	Sample date
40400301C1	INORG	Zinc	82.6		mg/kg		SOIL	INLET 2	0-0.5	7/18/95
40400501C1	INORG	Zinc	85.9		mg/kg		SOIL	INLET 3	0-0.5	7/18/95
40400701C1	INORG	Zinc	118		mg/kg		SOIL	INLET 4	0-0.5	7/18/95
4CC02401LA	INORG	Zinc	17.6		mg/kg	B	SOIL	POND 21	0-0.5	5/14/97
4CC02501LA	INORG	Zinc	9.9		mg/kg	B	SOIL	POND 22	0-0.5	5/14/97
4CC02601LA	INORG	Zinc	23.6		mg/kg	B	SOIL	POND 23	0-0.5	5/14/97
4CC02602LA	INORG	Zinc	31.1		mg/kg	B	SOIL	POND 23	0-0.5	5/14/97
4CC02701LA	INORG	Zinc	15.8		mg/kg	B	SOIL	POND 24	0-0.5	5/14/97
4CC02801LA	INORG	Zinc	14		mg/kg	B	SOIL	POND 25	0-0.5	5/14/97
4CC02901LA	INORG	Zinc	11.7		mg/kg	B	SOIL	POND 26	0-0.5	5/14/97
4CC03001LA	INORG	Zinc	10.1		mg/kg	B	SOIL	POND 27	0-0.5	5/14/97
4CC03101LA	INORG	Zinc	21.3		mg/kg	B	SOIL	POND 28	0-0.5	5/14/97
4CC03201LA	INORG	Zinc	20.5		mg/kg	B	SOIL	POND 29	0-0.5	5/14/97
4CC03301LA	INORG	Zinc	25.6		mg/kg	B	SOIL	POND 30	0-0.5	5/14/97
4CC03501LM	INORG	Zinc	81.6		mg/kg		SOIL	POND 32	0-0.5	7/16/97
4CC03601LM	INORG	Zinc	73.6		mg/kg		SOIL	POND 33	0-0.5	7/16/97
4CC03701LM	INORG	Zinc	89.4		mg/kg		SOIL	POND 34	0-0.5	7/16/97
4CC03801LM	INORG	Zinc	108		mg/kg		SOIL	POND 35	0-0.5	7/16/97
4CC03901LM	INORG	Zinc	108		mg/kg		SOIL	POND 36	0-0.5	7/16/97
4CC04001LM	INORG	Zinc	123		mg/kg		SOIL	POND 37	0-0.5	7/16/97
4CC04002LM	INORG	Zinc	131		mg/kg		SOIL	POND 37	0-0.5	7/16/97
40400201C1	INORG	Zinc	125		mg/kg		SOIL	INLET 2	0.17-0.67	7/18/95
40400202C1	INORG	Zinc	99.7		mg/kg		SOIL	INLET 2	0.17-0.67	7/18/95
40400401C1	INORG	Zinc	89.5		mg/kg		SOIL	INLET 2	0.17-0.67	7/18/95
HG523501C1	INORG	Zinc	223		mg/kg	EJ P	SOIL	SA 53	0-1	10/13/97
HG520501C1	INORG	Zinc	155		mg/kg	NJ P	SOIL	SA 23	0-1	10/8/97
HG521101C1	INORG	Zinc	147		mg/kg	NJ P	SOIL	SA 29	0-1	10/8/97
HG523601C1	INORG	Zinc	120		mg/kg	EJ P	SOIL	SA 54	0-1	10/13/97
HG522401C1	INORG	Zinc	118		mg/kg	P	SOIL	SA 42	0-1	10/9/97
HG520301C1	INORG	Zinc	115		mg/kg	NJ P	SOIL	SA 21	0-1	10/8/97
HG524102C1	INORG	Zinc	115		mg/kg	EJ P	SOIL	SA 59	0-1	10/13/97
HG521701C1	INORG	Zinc	113		mg/kg	P	SOIL	SA 36	0-1	10/9/97
HG521501C1	INORG	Zinc	104		mg/kg	P	SOIL	SA 33	0-1	10/9/97
HG521901C1	INORG	Zinc	104		mg/kg	P	SOIL	SA 37	0-1	10/9/97
HG522301C1	INORG	Zinc	104		mg/kg	P	SOIL	SA 41	0-1	10/9/97
HG522501C1	INORG	Zinc	102		mg/kg	P	SOIL	SA 43	0-1	10/9/97
HG521401C1	INORG	Zinc	101		mg/kg	P	SOIL	SA 32	0-1	10/9/97
HG523101C1	INORG	Zinc	101		mg/kg	P	SOIL	SA 49	0-1	10/9/97
HG523001C1	INORG	Zinc	100		mg/kg	P	SOIL	SA 48	0-1	10/9/97
HG521601C1	INORG	Zinc	100		mg/kg	P	SOIL	SA 34	0-1	10/9/97
HG522101C1	INORG	Zinc	99		mg/kg	P	SOIL	SA 39	0-1	10/9/97
HG522102C1	INORG	Zinc	98.9		mg/kg	P	SOIL	SA 39	0-1	10/9/97
HG521801C1	INORG	Zinc	98.5		mg/kg	P	SOIL	SA 36	0-1	10/9/97
HG521301C1	INORG	Zinc	96.5		mg/kg	P	SOIL	SA 31	0-1	10/9/97
HG523701C1	INORG	Zinc	94.3		mg/kg	EJ P	SOIL	SA 55	0-1	10/13/97
HG522201C1	INORG	Zinc	94.3		mg/kg	P	SOIL	SA 40	0-1	10/9/97
HG524101C1	INORG	Zinc	93.8		mg/kg	EJ P	SOIL	SA 59	0-1	10/13/97
HG522601C1	INORG	Zinc	90.1		mg/kg	P	SOIL	SA 44	0-1	10/9/97
HG522901C1	INORG	Zinc	88.3		mg/kg	P	SOIL	SA 47	0-1	10/9/97
HG520201C1	INORG	Zinc	87.5		mg/kg	NJ P	SOIL	SA 20	0-1	10/8/97
HG520101C1	INORG	Zinc	87.1		mg/kg	NJ P	SOIL	SA 19	0-1	10/8/97
HG523401C1	INORG	Zinc	86.9		mg/kg	EJ P	SOIL	SA 52	0-1	10/13/97
HG520801C1	INORG	Zinc	86.8		mg/kg	NJ P	SOIL	SA 26	0-1	10/8/97
HG522001C1	INORG	Zinc	86.7		mg/kg	P	SOIL	SA 38	0-1	10/9/97
HG521001C1	INORG	Zinc	86.3		mg/kg	NJ P	SOIL	SA 28	0-1	10/8/97
HG520102C1	INORG	Zinc	83.7		mg/kg	NJ P	SOIL	SA 19	0-1	10/8/97
HG521201C1	INORG	Zinc	80.6		mg/kg	P	SOIL	SA 30	0-1	10/9/97
HG522801C1	INORG	Zinc	80.2		mg/kg	P	SOIL	SA 46	0-1	10/9/97
HG523301C1	INORG	Zinc	80.2		mg/kg	EJ P	SOIL	SA 51	0-1	10/13/97
HG522701C1	INORG	Zinc	79.1		mg/kg	P	SOIL	SA 45	0-1	10/9/97
HG520701C1	INORG	Zinc	78.4		mg/kg	NJ P	SOIL	SA 25	0-1	10/8/97

Sample no.	Analysis	Compound	Conc	Rad uncrt	Units	Q flags	Matrix	Type location	Depth (ft)	Sample date
HG523801C1	INORG	Zinc	74.5		mg/kg	EJ P	SOIL	SA 56	0-1	10/13/97
HG524401C1	INORG	Zinc	72.6		mg/kg	EJ P	SOIL	SA 62	0-1	10/13/97
HG520401C1	INORG	Zinc	71.9		mg/kg	NJ P	SOIL	SA 22	0-1	10/8/97
HG520601C1	INORG	Zinc	70.1		mg/kg	NJ P	SOIL	SA 24	0-1	10/8/97
HG523201C1	INORG	Zinc	69.3		mg/kg	EJ P	SOIL	SA 50	0-1	10/13/97
HG524201C1	INORG	Zinc	69.1		mg/kg	EJ P	SOIL	SA 60	0-1	10/13/97
HG520901C1	INORG	Zinc	68.3		mg/kg	NJ P	SOIL	SA 27	0-1	10/8/97
HG523801N2	INORG	Zinc	62.7		mg/kg	EJ P	SOIL	SA 56	0-1	10/13/97
HG523901C1	INORG	Zinc	60.8		mg/kg	EJ P	SOIL	SA 57	0-1	10/13/97
HG524301C1	INORG	Zinc	60		mg/kg	EJ P	SOIL	SA 61	0-1	10/13/97
HG524001C1	INORG	Zinc	59.1		mg/kg	EJ P	SOIL	SA 57	0-1	10/13/97
HG520001C1	INORG	Zinc	58.6		mg/kg	NJ P	SOIL	SA 18	0-1	10/8/97
40400601C1	INORG	Zinc	111		mg/kg		SOIL	INLET 3	1.5	7/18/95
40400801C1	INORG	Zinc	68.7		mg/kg		SOIL	INLET 4	1.5	7/18/95
4CN03801C1	INORG	Zinc	70.6		mg/kg		SOIL	TRENCH 1 #4	3.5	6/2/97
4CN04301C1	INORG	Zinc	44		mg/kg		SOIL	TRENCH 2 #1	3.5	6/2/97
4CN03501C1	INORG	Zinc	55.5		mg/kg		SOIL	TRENCH 1 #1	4	6/2/97
4CN03701C1	INORG	Zinc	69.4		mg/kg		SOIL	TRENCH 1 #3	4	6/2/97
4CN03601C1	INORG	Zinc	68.7		mg/kg		SOIL	TRENCH 1 #2	4.5	6/2/97
4CN03602C1	INORG	Zinc	64.2		mg/kg		SOIL	TRENCH 1 #2	4.5	6/2/97
4CP06301LA	INORG	Zinc	12.7		mg/kg	B	SOIL	PIPE 4	5-7	5/14/97
4CN05101C1	INORG	Zinc	68.4		mg/kg		SOIL	TRENCH 3 #1	5.6	6/2/97
4CN05201C1	INORG	Zinc	65.5		mg/kg		SOIL	TRENCH 3 #2	6	6/2/97
4CN05401C1	INORG	Zinc	51		mg/kg		SOIL	TRENCH 3 #4	6.5	6/2/97
4CN05301C1	INORG	Zinc	62.2		mg/kg		SOIL	TRENCH 3 #3	6.8	6/2/97
4CN04601C1	INORG	Zinc	72.4		mg/kg		SOIL	TRENCH 2 #4	7	6/2/97
4CN04501C1	INORG	Zinc	59.7		mg/kg		SOIL	TRENCH 2 #3	7.5	6/2/97
4CN04401C1	INORG	Zinc	61.8		mg/kg		SOIL	TRENCH 2 #2	8	6/2/97
4CC01101LA	INORG	Zirconium	38		mg/kg	B	SOIL	POND 9	0-0.15	5/14/97
4CC00101LA	INORG	Zirconium	7.1		mg/kg	B	SOIL	POND 1	0-0.5	5/14/97
4CC00201LA	INORG	Zirconium	28		mg/kg	B	SOIL	POND 2	0-0.5	5/14/97
4CC00401LA	INORG	Zirconium	34.6		mg/kg	B	SOIL	POND 3	0-0.5	5/14/97
4CC00501LA	INORG	Zirconium	31.8		mg/kg	B	SOIL	POND 4	0-0.5	5/14/97
4CC00601LA	INORG	Zirconium	30.1		mg/kg	B	SOIL	POND 5	0-0.5	5/14/97
4CC00701LA	INORG	Zirconium	4.2		mg/kg	U	SOIL	POND 6	0-0.5	5/14/97
4CC00801LA	INORG	Zirconium	42		mg/kg	B	SOIL	POND 7	0-0.5	5/14/97
4CC00901LA	INORG	Zirconium	17.6		mg/kg	B	SOIL	POND 8	0-0.5	5/14/97
4CC01201LA	INORG	Zirconium	363		mg/kg		SOIL	POND 10	0-0.5	5/14/97
4CC01301LA	INORG	Zirconium	21.5		mg/kg	B	SOIL	POND 11	0-0.5	5/14/97
4CC01401LA	INORG	Zirconium	53.8		mg/kg	B	SOIL	POND 12	0-0.5	5/14/97
4CC01501LA	INORG	Zirconium	15.2		mg/kg	B	SOIL	POND 13	0-0.5	5/14/97
4CC01601LA	INORG	Zirconium	71.5		mg/kg	B	SOIL	POND 14	0-0.5	5/14/97
4CC01701LA	INORG	Zirconium	34.8		mg/kg	B	SOIL	POND 15	0-0.5	5/14/97
4CC01901LA	INORG	Zirconium	27		mg/kg	B	SOIL	POND 16	0-0.5	5/14/97
4CC02001LA	INORG	Zirconium	23.6		mg/kg	B	SOIL	POND 17	0-0.5	5/14/97
4CC02101LA	INORG	Zirconium	1570		mg/kg		SOIL	POND 18	0-0.5	5/14/97
4CC02201LA	INORG	Zirconium	52		mg/kg	B	SOIL	POND 19	0-0.5	5/14/97
4CC02301LA	INORG	Zirconium	41.6		mg/kg	B	SOIL	POND 20	0-0.5	5/14/97
4CP06401LA	INORG	Zirconium	17.7		mg/kg	*	SOIL	SA 1	0-0.5	6/3/97
4CP06501LA	INORG	Zirconium	39.3		mg/kg	*	SOIL	SA 2	0-0.5	6/3/97
4CP06601LA	INORG	Zirconium	22		mg/kg	*	SOIL	SA 3	0-0.5	6/3/97
4CP06701LA	INORG	Zirconium	13.4		mg/kg	*	SOIL	SA 4	0-0.5	6/3/97
4CP06702LA	INORG	Zirconium	8.6		mg/kg	*	SOIL	SA 4	0-0.5	6/3/97
4CP06801LA	INORG	Zirconium	23		mg/kg	*	SOIL	SA 5	0-0.5	6/3/97
4CP06901LA	INORG	Zirconium	23.9		mg/kg	*	SOIL	SA 60	0-0.5	6/3/97
4CP07001LA	INORG	Zirconium	13.6		mg/kg	*	SOIL	SA 7	0-0.5	6/3/97
4CP07101LA	INORG	Zirconium	23.9		mg/kg	*	SOIL	SA 8	0-0.5	6/3/97
4CP07201LA	INORG	Zirconium	11.4		mg/kg	*	SOIL	SA 9	0-0.5	6/3/97
4CP07301LA	INORG	Zirconium	26.6		mg/kg	*	SOIL	SA 10	0-0.5	6/3/97
4CP07401LA	INORG	Zirconium	10.7		mg/kg	*	SOIL	SA 11	0-0.5	6/3/97
4CP07501LA	INORG	Zirconium	19.8		mg/kg	*	SOIL	SA 12	0-0.5	6/3/97