



STATE OF IDAHO
DEPARTMENT OF
ENVIRONMENTAL QUALITY

1410 North Hilton • Boise, Idaho 83706 • (208) 373-0502

C.L. "Butch" Otter, Governor
Toni Hardesty, Director

January 3, 2012

Ms. Nicole Hernandez
Department of Energy IOO
1955 Fremont Avenue
Idaho Falls, ID 83415

Subject: Concurrence on Leaving Piping With Leaded Joints Beneath CPP-601 and CPP-602 As Impracticable to Remove at the INTEC CPP-601/627/640 Landfill Closure on the Idaho National Laboratory (EPA ID No. IDD4890008952)

Dear Ms. Hernandez:

The Idaho Department of Environmental Quality (DEQ) Hazardous Waste Program has completed a review of your November 7, 2011 submittal requesting concurrence on leaving leaded pipe joints beneath the floors of the closed and grouted CPP-601 landfill hazardous waste management unit.

The Hazardous Waste Program concurs that the piping with leaded joints is impracticable to remove. The residual lead must be added to the CPP-601/627/640 waste inventory.

If you have any questions concerning this concurrence, please contact Brian English at (208) 373-0425.

Sincerely,

A handwritten signature in black ink, appearing to read "Robert E. Bullock", written over a circular stamp.

Robert E. Bullock
Hazardous Waste Permits Manager
Waste Management and Remediation Division

REB:BLE:js

ConcurLeadedJntsCPP601

cc: Robbie Hedeem, USEPA Region 10
Dave Wessman, DOE
Daryl Koch, DEQ
INipwc
COF